

document_id: NMR-PRG-UTL-002 title: Boiler Handover Evidence Near-Miss Training Scenario
document_type: near_miss_report synthetic: true generated_for: Pragyan Plant Intelligence Hackathon
Prototype revision: "1.0" effective_or_event_date: 2025-08-23 owner_role: Maintenance Planner
related_asset_tags: [B-501, P-501] related_drawing_ids: [PCP-PID-004] confidentiality: Internal Demo

review_status: Draft for Human Review

Synthetic Training Scenario

This is a fictional maintenance-handover near-miss record for demonstration only. It does not describe a real boiler, pump, or maintenance event.

Event Details

Field	Value
Event ID	NMR-PRG-UTL-002
Event date	2025-08-23
Category	Handover evidence gap
Affected assets	B-501, P-501
Source drawing	PCP-PID-004
Follow-up owner role	Maintenance Planner
Status	Follow-up Open

Observed Facts

A fictional handover package identified B-501 and P-501 on the available P&ID, but a vendor-document reference was not available in the evidence index. The record does not conclude that maintenance was incomplete or that equipment condition was affected.

Immediate Non-Operational Actions

- Keep the unavailable reference visible as an evidence gap.
- Link the relevant P&ID and inspection record to the review task.
- Assign document follow-up ownership without changing asset status.

Evidence Gap

The fictional package lacks an accessible vendor-document reference required for a complete handover evidence trail.

Lessons Learned

Handover quality depends on accessible, traceable records. Missing documentation should remain visible rather than being replaced by an assumption.

Related Documents

SOP-PRG-UTL-003; SOP-PRG-MNT-002; INS-PRG-B501-001