

document_id: INS-PRG-C301-001 **title:** Distillation Column C-301 Follow-Up Review
document_type: inspection_report **synthetic:** true **generated_for:** Pragyan Plant Intelligence Hackathon Prototype **revision:** "1.0" **effective_or_event_date:** 2025-07-22
owner_role: Reliability Engineer **related_asset_tags:** [C-301, E-301]
related_drawing_ids: [PCP-PID-002] **confidentiality:** Internal Demo **review_status:** Draft for Human Review

Inspection Details

Field	Value
Inspection ID	INS-PRG-C301-001
Asset tag	C-301
Asset type	Distillation column
Drawing ID	PCP-PID-002
Inspector role	Reliability Engineer

Scope

Review the fictional documentation links between C-301, E-301, and PCP-PID-002.

Observations

The source-reference package contains a column and reboiler relationship but lacks a clear owner entry for one follow-up note. No process, temperature, pressure, or equipment-health conclusion is recorded.

Finding and Follow-Up

Severity: Needs Review

Recommended follow-up: Assign an owner role to the documentation follow-up and preserve the drawing reference in the linked asset record.

Review Status

Draft for Human Review. This is a synthetic inspection scenario, not a confirmed plant finding.