

document_id: INS-PRG-B501-001 **title:** Boiler B-501 and Feedwater Pump P-501 Handover Evidence Review **document_type:** inspection_report **synthetic:** true **generated_for:** Pragyan Plant Intelligence Hackathon Prototype **revision:** "1.0" **effective_or_event_date:** 2025-08-01 **owner_role:** Maintenance Planner **related_asset_tags:** [B-501, P-501] **related_drawing_ids:** [PCP-PID-004] **confidentiality:** Internal Demo **review_status:** Draft for Human Review

Inspection Details

Field	Value
Inspection ID	INS-PRG-B501-001
Asset tag	B-501
Asset type	Steam boiler
Drawing ID	PCP-PID-004

Inspector role	Maintenance Planner
Evidence references	SOP-PRG-UTL-003; SOP-PRG-MNT-002

Scope

Review the fictional handover evidence associated with B-501 and P-501.

Observations

The available fictional package links both assets to PCP-PID-004. A vendor-document reference is unavailable in the package and is recorded as an evidence gap. No inspection conclusion about boiler or pump condition is made.

Finding and Follow-Up

Severity: Needs Review
Recommended follow-up: Assign a documentation owner to request or confirm the unavailable reference before the next handover review.

Review Status

Draft for Human Review. This is a synthetic inspection scenario, not a

confirmed plant finding.