

2.5 Stock forms, types and sizes in order to calculate and determine the quantity of ferrous and non-ferrous metals required	To apply knowledge and understanding of the advantages, disadvantages and applications of the following forms/sizes of materials, in order to be able to discriminate between them and select appropriately.
	2.5.1 Stock forms/types: - a bar - b sheet - c plate - d pipe/tube - e castings - f extrusions - g wire - h powder metallurgy.
	2.5.2 Sizes: - a gauge - b cross-sectional area - c diameter - d wall thickness of tubes.