

4.5 Stock forms, types and sizes in order to calculate and determine the quantity of thermoforming and thermosetting polymers required	To apply knowledge and understanding of the advantages, disadvantages and applications of the following forms/sizes of materials, in order to be able to discriminate between them and select appropriately.
	4.5.1 Stock forms/types: - a bar - b sheet - c pipe/tube - d mouldings - e resin - f granules/powder - g film.
	4.5.2 Sizes: - a thickness - b cross-sectional area - c sheet size - d diameter.

POLYMERS

Key idea	What students need to learn:
----------	------------------------------