

MAYUR INDUSTRIES PVT.LTD.

parent part name	parent part number	number of child parts	OK Count	NOK Count	Time	Reason
AIR DUCT	2301CW500030M	7	1	0	17:36:32	None
AIR DUCT	2301CW500030M	7	0	1	17:37:59	5. Bracket Hole Absent/ Wrong Orientation
AIR DUCT	2301CW500030M	7	0	1	17:38:18	4. Bracket Hole Absent/ Wrong Orientation
AIR DUCT	2301CW500030M	7	0	1	17:38:33	4. Bracket Hole Absent/ Wrong Orientation and 5. Bracket Hole Absent/ Wrong Orientation
AIR DUCT	2301CW500030M	7	0	1	17:38:45	4. Bracket Hole Absent/ Wrong Orientation
AIR DUCT	2301CW500030M	7	1	0	17:39:04	None
AIR DUCT	2301CW500030M	7	1	0	17:39:41	None
AIR DUCT	2301CW500030M	7	0	1	17:40:20	5. Bracket Hole Absent/ Wrong Orientation
AIR DUCT	2301CW500030M	7	1	0	17:41:34	None
AIR DUCT	2301CW500030M	7	0	1	17:42:36	3. Foam Absent and 4. Bracket Absent/Wrong Orientation and 5. Bracket Hole Absent/ Wrong Orientation and 7. Hole Absent
AIR DUCT	2301CW500030M	7	0	1	17:43:12	3. Foam Absent and 4. Bracket Absent/Wrong Orientation and 5. Bracket Hole Absent/ Wrong Orientation and 6. Foam Absent and 7. Hole Absent
AIR DUCT	2301CW500030M	7	0	1	17:43:43	1. Hole Absent and 2. Bracket Absent/Wrong Orientation and 3. Foam Absent and 4. Bracket Absent/Wrong Orientation and 5. Bracket Absent/Wrong Orientation and 6. Foam Absent and 7. Hole Absent
AIR DUCT	2301CW500030M	7	0	1	17:43:51	3. Foam Absent and 4. Bracket Absent/Wrong Orientation and 5. Bracket Hole Absent/ Wrong Orientation and 7. Hole Absent

parent part name	parent part number	number of child parts	OK Count	NOK Count	Time	Reason
AIR DUCT	2301CW500030M	7	0	1	17:44:31	4. Bracket Hole Absent/ Wrong Orientation and 6. Foam Absent and 7. Hole Absent
AIR DUCT	2301CW500030M	7	0	1	17:45:03	4. Bracket Hole Absent/ Wrong Orientation and 6. Foam Absent and 7. Hole Absent
AIR DUCT	2301CW500030M	7	0	1	17:45:43	1. Hole Absent and 3. Foam Absent and 4. Bracket Absent/Wrong Orientation and 5. Bracket Hole Absent/ Wrong Orientation and 6. Foam Absent and 7. Hole Absent
AIR DUCT	2301CW500030M	7	0	1	17:46:23	5. Bracket Hole Absent/ Wrong Orientation
AIR DUCT	2301CW500030M	7	1	0	17:46:40	None
AIR DUCT	2301CW500030M	7	0	1	17:49:17	1. Hole Absent and 2. Bracket Absent/Wrong Orientation and 3. Foam Absent and 4. Bracket Absent/Wrong Orientation and 5. Bracket Absent/Wrong Orientation and 6. Foam Absent and 7. Hole Absent
AIR DUCT	2301CW500030M	7	0	1	17:49:26	1. Hole Absent and 2. Bracket Absent/Wrong Orientation and 3. Foam Absent and 4. Bracket Absent/Wrong Orientation and 5. Bracket Absent/Wrong Orientation and 6. Foam Absent and 7. Hole Absent

parent part name	parent part number	number of child parts	OK Count	NOK Count	Time	Reason
AIR DUCT	2301CW500030M	7	0	1	17:51:34	1. Hole Absent and 2. Bracket Hole Absent/ Wrong Orientation and 3. Foam Absent and 4. Bracket Absent/Wrong Orientation and 5. Bracket Absent/Wrong Orientation and 6. Foam Absent and 7. Hole Absent
AIR DUCT	2301CW500030M	7	0	1	17:52:00	1. Hole Absent and 2. Bracket Hole Absent/ Wrong Orientation and 3. Foam Absent and 4. Bracket Absent/Wrong Orientation and 5. Bracket Hole Absent/ Wrong Orientation and 6. Foam Absent and 7. Hole Absent
AIR DUCT	2301CW500030M	7	0	1	17:52:26	1. Hole Absent and 2. Bracket Hole Absent/ Wrong Orientation and 3. Foam Absent and 4. Bracket Absent/Wrong Orientation and 5. Bracket Hole Absent/ Wrong Orientation and 6. Foam Absent and 7. Hole Absent