

1. MACHINE IDENTIFICATION

The Press-2001 is a mechanical press; it has no hydraulic system.

Most fault codes are mechanical rather than hydraulic.

TROUBLESHOOTING

E101 on the Press-2001: drive chain binding.

Check the drive chain tension and sprocket alignment.

Source: Section 7, page 311.