





Refer to your written Project Notes for particular instructions.

Ensure you have the necessary equipment.

All safety requirements must be adhered to

Safety checks are frequently done.

Students without closed and proper shoes won't be assessed.

The record in your field notes must state whether all group member complied with the safety rules.

Boundary lines are set up at right angle and checked with 3, 4 & 5 rule

As soon as you have establish the four corner pegs, lay out the profiles

All profile crossheads are levelled and set up at a specified reduced level (RL)

Triangular shape is in line with the profile bar

Please handle the surveying equipment with care.

Keep the steel bars vertical when you hammer them in.

(You may use a staff bubble).



When you have finished checked everything mentioned on your Assessment sheet then contact your lecturer to assess your work