				SERIAL / PARALLEL RE	MOTE				
					NOTE.				
		XA1 1 0		L1 18UH		o ×c1	9		
				L2 T N					
		XA1 2 0		L2 IN C2		o ×⊏1	7		
				L3 IN IN					
		XA1 3 0				о хсі	5		
				L4 I2UH					
		XA1 4 0				—-o <sup>XС1</sup>	3		
	SUBD-9P-MALE	XA1 5 O		<u> </u>		o ×c1	1		
	SUBD-SF-WALE	^^1 3 0	İ						
				L5		— o <sup>хс1</sup>	10		
		XA1 6 0		L5 18UH		o XC1	8		
				L6 T 1N					
		XA1 7 O				——о <sup>ХС1</sup>	6		
				L7 IN IN					
		XAI B O				——о <sup>хс1</sup>	4		
		XA1 9 0		L8		o ×c1	2		
		5 0		L CB		0 ^=-	-		
				CHANGE OVER UNIT					
		XB1 1 0		L9 10UH		—o <sup>хд1</sup>	1		
				L 10 TN					
		XB1 2 0				O XD1	2		
				L11 T IN					
		XB1 3 O				O XD1	3		
		XB1 4 O		⊥ "`		O XD1	4		
	SUBD-9P-FEMALE	<sup>XB1</sup> <sup>5</sup> O	•			o ×D1	5		
		<sup>XB1</sup> 6 O				O XD1	6		
		<sup>XB1</sup> <sup>7</sup> O				O XDI			
		XB1 8 O				O XD1	8		
		XB1 9 O				O XD1	9		
						O XD1	10		
	XA1 10 O							ED IN : P	7 0636
	XAI II O			REMOTE	INTERFACE	4000	100 03	304	1 96- <del>86-</del> 10 2 96-11-29
	XBI 11 0								
	_		CHECK: AØ6361 .S A83Ø41 .P	NAME: PF/SMa	TV TEST EQUIPME		1 SH SH 130 605 BRONDBY		6-05-21 44
			1.00041 .11					12	