

Well Control Hub

The map of well-control tools, and which parts are built

⚠ FOR UNDERSTANDING PURPOSES ONLY

Prasanaa Kartick T — Personal Learning Project

Flutter / Dart

Kill sheets

SCR measurement

Shut-in

Kick detection

1. What It Is

Well Control is the most safety-critical area of the app and is coloured **red** in the Operations menu. It is reached from Operations › Drilling › Well Control, and also from Safety › Process Safety › Well Control. Both routes lead to the same screens.

A **kick** is an unplanned flow of formation fluid into the well. Well control is the set of procedures used to stop it safely.

2. The Five Areas

Area	Contents	Status
Kill Sheets	Surface Kill Sheet (IWCF · Surface BOP · Vertical Well) and Subsea Kill Sheet (IWCF · Subsea BOP · Vertical Well)	Built
SCR Measurement	Surface (SCR pressure at pump speed) and Subsea (riser margin and SCR pressure)	Built
Shut-in Procedures	Soft Shut-in Simulator (open choke, FOSV, then close choke) and Hard Shut-in Simulator (close FOSV, then annular or rams)	Coming soon
Kick Detection	Flow Test Simulator (trip in and out, flow check, indicators) and Pit Volume / Trip Tank Gain Simulator	Coming soon
Well Control Methods	Driller's Method (two circulations, original mud weight) and Wait & Weight Method (one circulation, kill weight mud)	Coming soon

3. How the Built Tools Fit Together

1. **Before a kick:** record the **SCR** — the standpipe pressure at slow pump speeds — using the SCR Measure screen.
2. **When a kick happens:** use the **Kill Sheet**. It takes the SCR pressure as an input, together with the well data and the shut-in pressures, and calculates the kill mud weight and the pressure schedule to follow.

Important note

These screens are learning and reference tools. In a real well-control event, calculations must be carried out by trained and certified personnel following the operator's procedures and the applicable regulations.

4. Related Documents

Document	Covers
SCR Measure — Surface	Slow-rate pressure recording for surface BOP wells
SCR Measure — Subsea	The same with riser margin and choke-line columns
Kill Sheet — Surface	The eight-calculation IWCF kill sheet and PDF
Kill Sheet — Subsea	The nine-calculation version with choke-line friction