Project M-121 Design Change Review

1 Background

Motor mounting bracket was lightened to reduce mass by 8 percent.

2.1 Post-Change Observations

Vibration increased after the mounting bracket modification. Bracket stiffness fell and a resonance appeared near 410 Hz.

3 Resolution

Added a gusset rib to restore stiffness; resonance moved above the operating range.