Table 1: Messdaten

$egin{array}{c} U \ V \end{array}$	Hhe cm	$egin{array}{c} U \ \mathrm{V} \end{array}$	$\frac{Hhe}{\mathrm{cm}}$	U V	Hhe cm	$egin{array}{c} U \ \mathrm{V} \end{array}$	Hhe cm	$egin{array}{c} U \ \mathrm{V} \end{array}$	$\frac{Hhe}{\mathrm{cm}}$
-7,3 -4,5 -1,6 1,1 3,6 6,2 8,8 11,4 14,0	1,5875 0,9525 0,3175 -0,3175 -0,9525 -1,5875 -2,2225 -2,8575 -3,4925	-12,3 -7,5 -2,7 2,4 6,9 11,4 16,2 20,8 25,6	1,524 0,889 0,254 -0,381 -1,016 -1,651 -2,286 -2,921 -3,556	16,4 10,5 -3,7 2,9 9,8 15,7 22,6 28,8 34,4	1,4478 0,8128 0,1778 -0,4572 -1,0922 -1,7272 -2,3622 -2,9972 -3,6322	-19,7 -11,3 -2,9 6,4 13,6 21,6 29,6	1,3462 0,7112 0,0762 -0,5588 -1,1938 -1,8288 -2,4638	-10,6 -0,9 8,6 17,9 27,0	0,635 0,0 -0,635 -1,27 -1,905