fcreate	R-type					
	funct7	rs2	rs1	funct3	rd	opcode
	"0000000"	unused	core num	"000"	status	"0001011"
fconn	R-type					
	funct7	rs2	rs1	funct3	rd	opcode
	"0000000"	unused	core num	"001"	status	"0001011"
fsend	R-type					
	funct7	rs2	rs1	funct3	rd	opcode
	"0000000"	timeout (cycles)	num_regs	"010"	status	"0001011"
frecv	R-type					
	funct7	rs2	rs1	funct3	rd	opcode
	"0000000"	timeout (cycles)	num_regs	"011"	status	"0001011"
fclose	R-type					
	funct7	rs2	rs1	funct3	rd	opcode
	"0000000"	unused	core_num	"100"	status	"0001011"