

flange

tool0

static

static calibrate transform

rgb_hand_link

rgb_hand_optical_frame
(data from sensor rgb_hand)

static