# TURBO IIHD: Air Filter PreCleaner

You may notice this if you have to change air filters more often than normal. Or, you may notice this by placing your and under the PreCleaner – at 1,000 rpms (and more so at higher rpms) there is a noticeable air flow under the ejector vents. If you feel no air flow, increase the rpms. If still no air flow, you may have build-up in the ejector vents.

Simply use a pick, knife or air pressure to remove the blockage. There are 4 vents at the bottom of each TURBO II PreCleaner. In extreme cases, remove the PreCleaner to thoroughly clean the vents with a pick and air pressure.

TURBO II upside down – see contamination build up in vents. This is debris that normally would have been in your air filter.

Estimated time to clean TURBO II vents: 5-10 minutes

In extreme cases of air-born contamination, it is possible to have build-up with the TURBO II PreCleaners. The beauty is that this is easily cleaned with a pick or knife and/or air pressure.

©2024 EcoProUSA.com | All rights reserved.

2443 W 12th Street, Suite 6, Tempe, AZ 85281 customerservice@ecoprousa.com (602) 820-5143