

# Contractor Site Access, Safety, and Security Handbook

|                 |                                                  |
|-----------------|--------------------------------------------------|
| Document number | CBPA-OPS-HB-014                                  |
| Revision        | 6                                                |
| Effective date  | July 1, 2026                                     |
| Supersedes      | Revision 5, January 2025                         |
| Issued by       | Office of Port Operations and Security           |
| Applies to      | All contractor, consultant, and vendor personnel |

Read this handbook in full before your first visit. Your sponsor will ask you to confirm that you have done so.

Synthetic training document. All names, organizations, and data are fictional.

## Contents

1. Purpose and Applicability
  2. Before Your First Visit
  3. Port Access Credential
  4. Escorted Visitors
  5. Safety Orientation
  6. Port Zones and Protective Equipment
  7. Vehicles and Parking
  8. Work Permits
  9. Photography, Drones, and Data Capture
  10. Information Security on Port Property
  11. Incident, Injury, and Near-Miss Reporting
  12. Weather, Wind, and Tide Restrictions
  13. Environmental Protection
  14. Hours of Access
  15. Violations and Enforcement
  16. Contacts
- Appendix A. First Visit Checklist
- Appendix B. Lead Time Summary
- Appendix C. Zone Descriptions
- Appendix D. Abbreviations

### Summary of changes in Revision 6

- The lead time for a Port Access Credential application has increased from 7 to 10 business days.
- Drone flights now require Harbor Master approval and 10 business days of notice.
- The wind limit for wharf and waterside work is now stated as a sustained wind speed, with a separate gust limit.
- Lost credentials and lost devices must now be reported to Port Security within 1 hour.

## 1. Purpose and Applicability

The Calder Bay Port Authority operates a working seaport. Vessels, cranes, heavy vehicles, rail movements, and energized utilities are present every day. This handbook sets out what contractor personnel must do to enter port property, to work safely while they are there, and to protect the security of the port and the people who work in it.

The handbook applies to every person who is not a Port Authority employee and who enters port property to perform work. This includes contractors, subcontractors, consultants, inspectors, surveyors, delivery drivers who leave their vehicles, and vendor technicians. It applies for the full duration of a contract, including mobilization and demobilization.

Each contractor has a Port Authority sponsor. The sponsor is the Port Authority employee who is responsible for the contract or task order. The sponsor confirms that the contractor's personnel need access, supports their applications, and is the first point of contact for questions about this handbook.

Nothing in this handbook reduces a contractor's own legal duty to protect its workers. Where the contractor's safety program is stricter than this handbook, the stricter rule applies. Where a contract contains a specific requirement that differs from this handbook, the contract governs and the sponsor must be told.

## 2. Before Your First Visit

Most delays on a first visit are caused by steps that were started too late. The steps below are listed in the order they should be started. Lead times are stated in business days and do not include port holidays.

- 1 Ask your sponsor to register you in the Contractor Access Portal.
- 2 Submit your Port Access Credential application at least 10 business days before your first visit (Section 3).
- 3 Book a safety orientation session at least 3 business days ahead (Section 5).
- 4 Apply for a vehicle pass if you will drive beyond the contractor parking lot (Section 7).
- 5 Confirm with your supervisor which work permits your task requires and submit them with the lead times in Section 8.
- 6 Request a photography permit if your work involves any camera, including a phone camera or a drone (Section 9).
- 7 Obtain the protective equipment required for the zone in which you will work (Section 6).

If you cannot complete steps 2 and 3 in time, you may still attend as an escorted visitor under Section 4. Escorted visitors cannot perform unescorted work and cannot operate equipment.

### 3. Port Access Credential

The Port Access Credential, known as a PAC, is the photo identification badge that allows unescorted access to the zones printed on it. A PAC is issued to an individual and may not be lent, shared, or copied.

#### How to apply

- Apply through the Contractor Access Portal at least 10 business days before your first visit.
- Upload a government-issued photo identification document and a recent photograph.
- Your sponsor confirms the application in the portal. An application without sponsor confirmation is not processed.
- A background screening is carried out by Port Security. Screening normally takes 5 to 7 business days of the 10.
- The application fee is \$85 and is not refundable.

#### Collection and validity

- Collect your PAC in person at the Gatehouse 2 Credential Office, Monday through Friday, 6:30 AM to 3:00 PM. Bring the same identification document you uploaded.
- A PAC is valid for 12 months from the date of issue, or until the end of your contract if that is sooner.
- Wear the PAC above the waist and visible at all times on port property.
- Renew through the portal at least 10 business days before expiry. An expired PAC is deactivated automatically at midnight.
- A lost PAC must be reported to Port Security within 1 hour. The replacement fee is \$40.

#### Zones on your credential

Your PAC is encoded for the zones your sponsor has requested. Access to Zone D is never included by default and requires a separate written request from the sponsor to the Port Security Manager.

## 4. Escorted Visitors

A person without a PAC may enter port property only as an escorted visitor. The escort must hold a valid PAC for the zone being visited and must stay with the visitor at all times.

- The sponsor or escort requests a day pass through the portal at least 24 hours before the visit.
- Day passes are collected at Gatehouse 2 on arrival. Visitors must show government-issued photo identification.
- One escort may accompany no more than 5 visitors.
- A person may make no more than 3 escorted visits in any 90-day period. After the third visit a PAC is required.
- Escorted visitors may observe and attend meetings. They may not perform work, operate equipment, or enter Zone D.
- Escorted visitors receive a 10-minute safety briefing from the escort before leaving the gatehouse.

## 5. Safety Orientation

Every PAC holder must complete the Port Authority safety orientation before unescorted access is activated. The PAC is issued in an inactive state and is activated when the orientation record is entered.

- Sessions are held every Tuesday and Thursday at 7:00 AM in the Gatehouse 2 Training Room.
- A session lasts 90 minutes and ends with a short quiz. The pass mark is 80 percent.
- Book through the portal at least 3 business days ahead. Sessions are limited to 20 people.
- Orientation is valid for 24 months. A refresher is required after any Tier 2 violation (Section 15).
- Bring your own hard hat, high-visibility vest, and safety-toe boots. The session includes a short walk through Zone B.

The orientation covers traffic and pedestrian routes, crane and vessel operations, emergency signals and muster points, the zone system, permit requirements, reporting, and the security rules in Sections 9 and 10.

## 6. Port Zones and Protective Equipment

Port property is divided into four zones. Zone boundaries are marked by painted lines, signs, and gates. The minimum personal protective equipment for each zone is shown below. A task-specific hazard assessment may require more.

| Zone | Areas                                                                  | Minimum protective equipment                                                                                                    | Access                                                   |
|------|------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------|
| A    | Administration building, public areas, contractor parking Lot C        | Closed-toe shoes                                                                                                                | Day pass or PAC                                          |
| B    | Container yard, warehouses, maintenance shops, internal roads          | Hard hat, Class 2 high-visibility vest, safety-toe boots, eye protection                                                        | PAC with Zone B                                          |
| C    | Wharf, apron, berths, fender system, under-deck and waterside areas    | All Zone B equipment, plus a personal flotation device when within 10 feet of the water's edge, plus gloves when handling lines | PAC with Zone C                                          |
| D    | Substations, pump houses, fuel farm, security and communications rooms | All Zone B equipment, plus arc-rated clothing where posted                                                                      | PAC with Zone D and a Port Utilities escort at all times |

- Personal flotation devices must be United States Coast Guard approved, Type III or Type V, and must be worn fastened.
- Hearing protection is required wherever posted and within 50 feet of an operating ship-to-shore crane.
- Loose clothing, open footwear, and headphones are not permitted in Zones B, C, or D.
- No person may walk under a suspended load or between a container and a moving vehicle.

## 7. Vehicles and Parking

Personal vehicles must be parked in contractor Lot C, inside Gatehouse 2. A free shuttle runs from Lot C to the yard and the wharf every 20 minutes between 5:45 AM and 6:15 PM.

- A vehicle that will travel beyond Lot C requires a vehicle pass. Apply through the portal at least 5 business days ahead.
- Proof of automobile liability insurance with a combined single limit of at least \$2,000,000 is required for a vehicle pass.
- The speed limit is 15 miles per hour in the yard and on internal roads, and 5 miles per hour on the wharf apron.

- Vehicles on the apron must display an amber beacon and must give way to cranes, yard tractors, and rail movements.
- Personal vehicles are never permitted in Zone C or Zone D.
- Drivers must not use a handheld phone while the vehicle is moving anywhere on port property.

## 8. Work Permits

Certain activities require a permit from Port Operations before work begins. Permits are requested through the portal by the contractor's supervisor. The lead times below are minimums. A permit is valid only for the dates, location, and activity stated on it.

| Activity                              | Minimum notice   | Approver                           | Additional conditions                                                                 |
|---------------------------------------|------------------|------------------------------------|---------------------------------------------------------------------------------------|
| Hot work (welding, cutting, grinding) | 48 hours         | Port Operations                    | Fire watch for 60 minutes after work ends                                             |
| Work at height above 6 feet           | 48 hours         | Port Operations                    | Fall protection plan attached to the request                                          |
| Confined space entry                  | 72 hours         | Port Operations and Port Utilities | Atmospheric testing record and rescue plan                                            |
| Crane lift over 5 tons                | 72 hours         | Port Operations                    | Lift plan signed by a qualified person                                                |
| Excavation or ground disturbance      | 5 business days  | Port Engineering                   | Utility locate completed before work                                                  |
| Diving operations                     | 5 business days  | Harbor Master                      | Vessel traffic coordination and dive plan                                             |
| Drone (unmanned aircraft) flight      | 10 business days | Harbor Master                      | Remote pilot certificate, maximum altitude 200 feet, no flight over a vessel at berth |
| After-hours or Sunday work            | 2 business days  | Port Operations                    | Named supervisor on site                                                              |

A permit may be suspended at any time by Port Operations, the Harbor Master, or Port Security. When a permit is suspended, work stops immediately and the area is made safe.

## 9. Photography, Drones, and Data Capture

The port is a regulated facility. Images and recordings can reveal security arrangements, cargo, and the identity of vessels and customers. For that reason, all image capture on port property is controlled.

- A photography permit is required for any still or video capture, including on a phone, a tablet, or a drone.
- A photography permit may be requested with the PAC application, or separately with 3 business days of notice.
- Contractors whose contract requires them to photograph port assets, such as condition inspectors, are issued a standing photography permit for the contract period. The permit lists the asset types that may be photographed.
- It is prohibited to capture images of gates, fences, cameras, access control equipment, security personnel, or any part of Zone D.
- Port Security may ask to review images before they leave port property. A review is completed within 3 business days.
- Images must not be posted on social media or shared with anyone outside the contract.

## Drones

A drone flight requires both a photography permit and a drone flight permit under Section 8. The Harbor Master approves each flight window against the vessel schedule. The remote pilot must hold a current remote pilot certificate and must carry it on site. Flights are limited to 200 feet above ground or water level and are not permitted over a vessel at berth, over the fuel farm, or within Zone D. An unauthorized drone flight is a Tier 3 violation.

## 10. Information Security on Port Property

- Contractor devices may connect only to the guest wireless network named CBPA-Guest. The guest network provides internet access only.
- Contractor devices must never be connected to a Port Authority operational network, network port, or control system, by cable or wirelessly.
- Removable media, including USB drives and memory cards, are not permitted in Zone D.
- Do not leave laptops, tablets, or documents unattended in vehicles or in shared areas.
- Report a lost or stolen device that holds port information to Port Security within 1 hour of noticing the loss.
- Information provided by the Port Authority and marked as sensitive must be handled as the marking and the contract require, and returned or destroyed at the end of the contract.

Contractors that operate their own data collection systems on port property, such as inspection tablets, are responsible for the security of those systems and must tell their sponsor about any



data incident that involves port information within one business day.

## 11. Incident, Injury, and Near-Miss Reporting

Report first, then make the area safe if you can do so without risk. The Port Operations Center is staffed 24 hours a day.

| Event                                                                 | Report to                                                                   | When                    | Follow-up                                     |
|-----------------------------------------------------------------------|-----------------------------------------------------------------------------|-------------------------|-----------------------------------------------|
| Emergency: fire, serious injury, person in the water, security threat | Port Operations Center, 555-0144, or extension 4400 from any port telephone | Immediately             | Remain at a safe distance and meet responders |
| Any injury, however minor                                             | Port Operations Center and your supervisor                                  | Immediately             | Written report within 24 hours                |
| Near miss or unsafe condition                                         | Your supervisor and the sponsor                                             | Same shift              | Written report within 48 hours                |
| Spill of any quantity into the water                                  | Port Operations Center                                                      | Immediately             | Do not attempt to disperse                    |
| Spill on land of more than 1 gallon                                   | Port Operations Center                                                      | Immediately             | Contain with a spill kit if safe              |
| Property or equipment damage                                          | Port Operations Center and the sponsor                                      | Before leaving the site | Written report within 24 hours                |

The emergency signal is a continuous siren. On hearing it, stop work, make equipment safe, and walk to the nearest muster point. Muster points are marked with green signs and are shown on the map given out at orientation. Do not leave the muster point until your supervisor has accounted for you.

## 12. Weather, Wind, and Tide Restrictions

| Condition                                                                | Restriction                                                                       |
|--------------------------------------------------------------------------|-----------------------------------------------------------------------------------|
| Sustained wind above 30 miles per hour                                   | Crane operations stop                                                             |
| Sustained wind above 35 miles per hour, or gusts above 45 miles per hour | All wharf and waterside work is suspended                                         |
| Lightning within 10 miles                                                | Outdoor work stops. Work resumes 30 minutes after the last strike within 10 miles |
| Visibility below 500 feet                                                | Vehicle movement on the apron is suspended                                        |
| Heat index above 100 degrees Fahrenheit                                  | Mandatory rest and water breaks as directed by Port Operations                    |
| Ice or snow on the apron                                                 | Waterside work suspended until Port Operations declares the surface safe          |

Under-deck and waterside inspections may take place only when the tide is below 2.0 feet above mean lower low water. Tide windows are published by the Harbor Master each Friday for the following two weeks. Inspectors must book a tide window through the Harbor Master's office and must be clear of the under-deck area 30 minutes before the window closes.

Port Operations announces weather restrictions on the port radio channel and by text message to registered supervisors. A restriction applies from the moment it is announced.

## 13. Environmental Protection

- Nothing may be discharged, swept, or washed into the water or into a storm drain.
- Each work crew in Zone C must have a spill kit within 50 feet of the work.
- Fuel, oil, paint, and chemicals must be stored in secondary containment and removed from the port at the end of the task.
- Waste must be removed by the contractor unless the sponsor has agreed in writing to the use of port waste containers.
- Work that may disturb sediment, marine growth, or nesting birds requires advance agreement from the Port Environmental Officer.

## 14. Hours of Access

Standard hours of access for contractor personnel are 6:00 AM to 6:00 PM, Monday through Saturday. Access on Sundays, on port holidays, or outside standard hours requires an after-hours permit under Section 8, requested at least 2 business days ahead.

The Gatehouse 2 Credential Office is open Monday through Friday, 6:30 AM to 3:00 PM. Gatehouse 2 itself is staffed 24 hours a day. Gatehouse 1 is for cargo traffic only and must not be used by contractor personnel.

Port holidays in the second half of 2026 are September 7, October 12, November 11, November 26, and December 25.

## 15. Violations and Enforcement

The Port Authority applies a three-tier system. The tier is decided by Port Security and Port Operations together, taking into account the risk created and whether the violation was reported honestly.

| Tier   | Examples                                                                                                                                                              | Consequence                                                                |
|--------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------|
| Tier 1 | Missing or incorrect protective equipment, PAC not visible, parking outside Lot C, speeding by less than 10 miles per hour                                            | Written warning to the individual and the contractor                       |
| Tier 2 | Second Tier 1 violation within 12 months, working without a required permit, entering a zone not on the PAC, unreported near miss                                     | PAC suspended for 30 days and a refresher orientation before reinstatement |
| Tier 3 | Unauthorized drone flight, photographing security infrastructure, bypassing access control, lending a PAC, alcohol or drugs, weapons, tampering with safety equipment | PAC permanently revoked and the contractor notified in writing             |

A contractor whose personnel receive three or more Tier 2 or Tier 3 violations in a 12-month period will be asked to present a corrective action plan to the Director of Port Operations.

## 16. Contacts

| Office                            | Telephone                           | Use for                                                          |
|-----------------------------------|-------------------------------------|------------------------------------------------------------------|
| Port Operations Center (24 hours) | 555-0144, or extension 4400 on site | Emergencies, injuries, spills, weather restrictions              |
| Port Security (24 hours)          | 555-0162                            | Lost credentials, lost devices, security concerns, image reviews |
| Gatehouse 2 Credential Office     | 555-0118                            | PAC applications, collection, day passes, vehicle passes         |
| Harbor Master's Office            | 555-0171                            | Tide windows, diving, drone flights, vessel schedule             |
| Port Utilities                    | 555-0139                            | Zone D escorts, energized work, confined spaces                  |
| Port Environmental Officer        | 555-0156                            | Spill follow-up, sediment and wildlife questions                 |
| Contractor Access Portal help     | 555-0103                            | Portal accounts and application status                           |

## Appendix A. First Visit Checklist

Use this checklist with your supervisor. Every item must be complete before unescorted work begins.

| Item                                                              | Where                         | Done |
|-------------------------------------------------------------------|-------------------------------|------|
| Registered in the Contractor Access Portal by the sponsor         | Portal                        |      |
| PAC application submitted with identification and photograph      | Portal                        |      |
| Application fee of \$85 paid                                      | Portal                        |      |
| Safety orientation booked and attended                            | Gatehouse 2 Training Room     |      |
| PAC collected in person                                           | Gatehouse 2 Credential Office |      |
| Vehicle pass issued, if driving beyond Lot C                      | Portal                        |      |
| Photography permit issued, if capturing any image                 | Portal                        |      |
| Work permits approved for the planned activities                  | Portal                        |      |
| Protective equipment for the assigned zone obtained and inspected | Contractor                    |      |
| Emergency number saved: 555-0144                                  | Personal phone                |      |
| Tide window booked, for under-deck or waterside work              | Harbor Master's Office        |      |

## Appendix B. Lead Time Summary

| Requirement                                 | Minimum lead time              |
|---------------------------------------------|--------------------------------|
| Port Access Credential application          | 10 business days               |
| Port Access Credential renewal              | 10 business days before expiry |
| Drone flight permit                         | 10 business days               |
| Vehicle pass                                | 5 business days                |
| Excavation permit                           | 5 business days                |
| Diving operations permit                    | 5 business days                |
| Safety orientation booking                  | 3 business days                |
| Photography permit, if requested separately | 3 business days                |
| Confined space entry permit                 | 72 hours                       |
| Crane lift over 5 tons                      | 72 hours                       |
| Hot work permit                             | 48 hours                       |
| Work at height permit                       | 48 hours                       |
| After-hours or Sunday work                  | 2 business days                |
| Escorted visitor day pass                   | 24 hours                       |

## Appendix C. Zone Descriptions

**Zone A, Administrative and Public.** The administration building, the visitor center, the Gatehouse 2 Training Room and Credential Office, and contractor parking Lot C. Zone A is separated from operating areas by fencing and controlled gates. Pedestrians have priority on marked walkways.

**Zone B, Yard and Warehouse.** The container yard, Warehouses 1 through 4, the maintenance shops, and the internal road network. Yard tractors and top loaders operate continuously and have limited visibility. Pedestrians must use the green walkways and must make eye contact with an operator before crossing a traffic lane.

**Zone C, Wharf and Waterside.** Berths 1 through 6, the wharf apron, the fender system, the under-deck structure, and the water within 100 feet of the wharf face. Ship-to-shore cranes travel on rails along the apron and sound an alarm when moving. Mooring lines under tension are a serious hazard. Do not stand in line with a mooring line.

**Zone D, Restricted Utility and Security.** Substations 1 and 2, the pump houses, the fuel farm, and the security and communications rooms. Entry is by escort only. Mobile phones must be switched off in the fuel farm.

## Appendix D. Abbreviations

| Abbreviation | Meaning                                                     |
|--------------|-------------------------------------------------------------|
| CBPA         | Calder Bay Port Authority                                   |
| PAC          | Port Access Credential                                      |
| PFD          | Personal flotation device                                   |
| PPE          | Personal protective equipment                               |
| MLLW         | Mean lower low water, the tidal datum used for tide windows |
| UAS          | Unmanned aircraft system, commonly called a drone           |
| POC          | Port Operations Center                                      |