QUALITY & PROCESS

Internal Use Only

7 Quality Tools

Seven graphical techniques for understanding and solving quality problems: Fishbone, Pareto, Run Chart, Histogram,



WHEN TO USE

Whenever quality data exists and patterns, causes, or variation need to be understood visually before deciding on action.

HOW TO APPLY — STEPS

1. Select the right tool for the specific question being asked
2. Collect clean, stratified data from the process
3. Build the chart using real data — not estimates
4. Interpret the patterns objectively
5. Use findings to direct root cause analysis and action

PRACTITIONER TIP

Start with a Pareto — it instantly shows where 80% of the problem lives. Don't analyse everything equally.

KEY OUTPUTS

- Pareto chart
- Fishbone diagram
- Control chart or run chart
- Histogram
- Check sheet

HOW TO MEASURE SUCCESS

Defect reduction in the prioritised category; time from problem detection to root cause identified

TOOL CATEGORY

Quality & Process