QUALITY & PROCESS

Internal Use Only

Waste Identification

Identify and quantify the 8 wastes (TIMWOODS) — Transport, Inventory, Motion, Waiting, Overproduction, Over-processing,



WHEN TO USE

During gemba walks, process reviews, or when looking for cost reduction and lead time improvement opportunities.

HOW TO APPLY — STEPS

1. Train the team on all 8 waste types with real examples
2. Walk the process physically — never observe from a desk
3. Record each waste observed with frequency and estimated cost impact
4. Prioritise the top three wastes by total impact
5. Launch targeted improvement actions for each priority waste

PRACTITIONER TIP

! The 8th waste — unused human talent and creativity — is the most expensive and most overlooked waste in organisations.

KEY OUTPUTS

- Waste observation sheet
- Estimated waste cost by type
- Improvement priority list

HOW TO MEASURE SUCCESS

Estimated waste cost eliminated; process lead time reduction %; value-added ratio before and after

TOOL CATEGORY

Quality & Process