


## Bias and Resolution



The 16 most important features size length · kurtosis\_x kurtosis y stddev\_x stddev\_y clusters · width · skewness y skewness\_x area · mean\_y mean\_x cog x cog\_y angle -0.2 0.1 0.3 0.4 0.0 Feature importances