February 20, 2026

Kempsville Volunteer Rescue Squad

Attn: Lucas Priest, NRAEMT

5145 Ruritan Ct., Virginia Beach, VA 23462

Dear Lucas Priest, NRAEMT,

This letter is written in regard to the status of your Model 6506 Power-PRO XT, serial number 2003003500246 (collectively the "Products"), manufactured by Stryker Corporation's Medical division ("Stryker" or "we").

Under normal use conditions Stryker products are warranted to perform to their specifications for the duration of their expected service life; however, there are extenuating circumstances and events that may alter the performance of the products. Such is the case when the product is involved in an ambulance accident.

Stryker has received the Ambulance Accident Attestation related to the circumstances surrounding the ambulance accident which involved the Product(s) listed above. In reference to this ambulance accident, one of the following occurred:

- The Stryker Service Team performed a basic post-ambulance accident inspection of the Product(s) and determined that the Product(s) meet the specified criteria detailed in the preventative maintenance checklist of the Product's Operations and Maintenance manual*
- The Product(s) passed the expanded post-ambulance accident inspection. The recommended repairs following the post-ambulance accident inspection were completed

Since the Product(s) meet one or more of the above criteria and meet the specifications outlined in the Operations and Maintenance manuals, the Product(s) can continue to be used in accordance with its intended use.

If you have any questions, please, contact me.

Sincerely,

Alex Wibert

Alex Wibert
Stryker Medical
Regulatory Affairs

Stryker Medical
3800 E. Centre Ave, Portage, MI. 49002 USA | F +1 269 389 2213 | stryker.com

*For additional information regarding Stryker's ambulance accident policy and inspections offered please refer to Stryker's "Ambulance Accident Policy Explained" memo (Mkt Lit – 1414).