Allstate Insurance Company

P.O. Box 660636
Dallas, TX 75266
Fax: 866-447-4293
www.myclaim.com

Insured:	EARLINE COTTRELL
Property:	39675 PATTERSON LN CLEVELAND, OH 44139-6705
Home:	39675 PATTERSON LN CLEVELAND, OH 44139-6705

Claim Rep.:	Tyler Palmer	Business:	(936) 406-5813
Business:	PO BOX 672041 Dallas, TX 75267	E-mail:	claims@claims.allstate.com

Estimator:	Tyler Palmer	Business:	(936) 406-5813
Business:	PO BOX 672041 Dallas, TX 75267	E-mail:	claims@claims.allstate.com

Claim Number: 0820001477 **Policy Number:** 000880011591 **Type of Loss:** Windstorm and Hail

Insurance Company: Allstate Vehicle and Property Insurance Company

Date Contacted:	3/3/2026 1:49 PM		
Date of Loss:	1/19/2026 4:00 PM	Date Received:	2/24/2026 6:13 PM
Date Inspected:		Date Entered:	2/25/2026 7:34 AM

Price List:	OHCL8X_MAR26 Restoration/Service/Remodel
Estimate:	EARLINE_COTTRELL

Allstate is dedicated to providing you with outstanding service throughout the claim-handling process. If you have any questions regarding this estimate, or if there are differences with the estimate provided by your repair person of choice, or if additional damage is found during the repair process, please contact us at (936) 406-5813. or email us at claims@claims.allstate.com. If you are emailing us, please include the Claim Number in the subject line.

Thank you,
Tyler Palmer

THIS ESTIMATE REPRESENTS OUR CURRENT EVALUATION OF THE COVERED DAMAGES TO YOUR INSURED PROPERTY AND MAY BE REVISED AS WE CONTINUE TO EVALUATE YOUR CLAIM. IF YOU HAVE QUESTIONS, CONCERNS, OR ADDITIONAL INFORMATION REGARDING YOUR CLAIM, WE ENCOURAGE YOU TO CONTACT US.

Your guide to reading your adjuster summary.*

Allstate Insurance Company
PO Box 12345
Anytown, Anystate 12345

Insured: John Smith
Property: 1234 Oak Street
Anytown, Anystate 12345

Home: (123) 123-4567
Business: (123) 123-4567

A **Claim Number:** 123456789 **Policy Number:** 9876543210 **Type of Loss:** Windstorm



B

Main Home - Roof

Description	Quantity	Unit (C)	RCV (D)	Age/Life (H)	Condition (G)	Dep%	Deprec. (F)	ACV (E)
1. Remove Laminated – comp. shingle rfg. – w/out felt	11.50 SQ	40.22	462.53	0/30 yrs	Avg.	NA	(0.00)	462.53
2. Laminated – comp. shingle rfg.– w/out felt	12.67 SQ	149.19	1,890.24	0/30 yrs	Avg.	0%	(0.00)	1,890.24
Auto Calculated Waste: 10.2%, 1.17 SQ								
Options: Valleys: Closed-cut (half laced), Include eave starter course: Yes, Include rake starter course: No, Exposure: 5 5/8", Bundle Rounding: 2.3%, 0.26SQ - (included in waste calculation above)								
3. Roofing felt – 15lb	11.50 SQ	19.98	229.77	0/20 yrs	Abv. Avg.	0%	(0.00)	229.77
4. R&R Valley metal	16.28 LF	4.19	68.22	0/35 yrs	Abv. Avg.	0%	(0.00)	68.22
Total: Roof1			**$2650.76**				**(0.00)**	**$2,650.76**

Room 1

I

Description	Quantity	Unit	RCV	Age/Life	Condition	Dep%	Deprec.	ACV
5. Content Manipulation charge – per hour	10.00 HR	32.51	325.10	5/NA	Avg.	0%	(0.00)	325.10
6. Mask Wall – plastic, paper, tape (per LF)	528.LF	0.92	485.76	5/150 yrs	Avg.	3.33	(16.19)	469.57
7. Floor protection – plastic and tape – 10 mil	528.00 SF	0.24	126.72	5/15 yrs	Abv. Avg.	33.33%	(42.24)	84.48
8. R&R Batt insulation – 10" – R30 – paper faced	144.00 LF	1.62	233.28	5/150 yrs	Abv. Avg.	3.33%	(6.58)	226/70
Total: Room1		J	**$1,170.86**				**($65.01)**	**$1,105.85**

© Xactware

SAMPLE

A. CLAIM NUMBER
The claim number assigned to your loss.

B. DAMAGE LOCATION
The area that has been damaged.

C. UNIT COST
This amount reflects the cost of an item.

D. REPLACEMENT COST VALUE
Cost to repair or replace covered property damages.

E. ACTUAL CASH VALUE
This amount reflects the Replacement Cost Value less the amount of any Depreciation.

F. DEPRECIATION
This amount reflects any deductions from Replacement Cost Value to account for the decrease in the property's value due to various factors including, but not limited to, age, life expectancy, wear and tear (condition), and functional or economic obsolescence. Depreciation may apply to both Structure and Contents items. Your estimate was completed based on the information you provided regarding the age and condition of the depreciated items.

G. CONDITION
The category or state of an item with regard to its appearance, quality, or working order. Condition options are new, above average, average and below average.

H. AGE
This represents the age and average life expectancy of the particular line item at the time of loss.

I. REPAIR OR REPLACE ACTIONS
Describes the repairs and/or replacement materials and actions.

J. DAMAGE LOCATION TOTALS
Total before adding any applicable taxes and/or depreciation.

LF = Linear Feet **SQ** = 100 Square Feet **SF** = Square Feet **SY** = Square Yard **EA** = Each

*This is a sample guide to your adjuster summary

Allstate Insurance Company, Allstate Indemnity Company, Allstate Fire and Casualty Insurance Company, Allstate Property and Casualty Insurance Company, Northbrook, IL.
©2018 Allstate Insurance Company allstate.com 09/2018

Internal Information

Factor Detail

Roof Surface Payment Schedule (RPS)

Main Level - Roof1

Description	RPS Factor (K)	Quantity	Unit Price	Total	RPS Total
53. Laminated – comp. shingle rfg. – w/out felt Auto Calculated Waste: 10.2%, 1.17SQ	24%	12.67SQ	149.19	1,890.24	453.66
Options: Valleys: Closed-cut (half laced), Include eave starter course: Yes, Include rake starter course: No, Exposure: 5 5/8", Bundle Rounding: 2.3%, 0.26SQ - (included in waste calculation above)					
54. Roofing felt – 15 lb.	24%	11.50SQ	19.98	229.77	55.14
55a. Remove Valley Metal	N/A	16.28LF	0.42	6.84	6.84
55b. Valley Metal	24%	16.28LF	3.77	61.38	14.73
Line Item Total				$2,188.23	$530.37
Material Sales Tax				64.70	15.68
General Contractor Overhead				225.29	54.61
General Contractor Profit (L)				225.29	54.61
Total Tax				0.00	0.00
Replacement Cost Value				$2,703.51	
RPS Value					$655.27

Room 1

Unfactored Items

Description	Quantity	Unit Price	RCV	Depreciation	ACV
51. Remove Laminated - comp. shingle rfg. - w/out felt	11.50 SQ	40.22	462.53	0.00	462.53
71. Content Manipulation charge - per hour	10.00 HR	75.00	750.00	0.00	750.00
73. Mask wall - plastic, paper, tape (per LF)	528.00 LF	0.92	485.76	16.19	469.57
75. Floor protection - plastic and tape - 10 mil	528.00 SF	0.24	126.72	42.24	84.48
77a. Remove Batt insulation - 10" - R30 - paper faced	144.00 SF	0.25	36.00	0.00	36.00
77b. Batt insulation - 10" - R30 - paper faced	144.00 SF	1.37	197.28	6.58	190.70
Subtotal			$2,058.29	$65.01	
Material Sales Tax			4.89	0.00	
General Contractor Overhead			205.83	6.50	
General Contractor Profit			205.83	6.50	
Total Tax			169.81	0.00	
Replacement Cost Value (M)			$2,644.65		
Less Depreciation				($78.01)	
Actual Cash Value					$2,566.64

© Xactware

K. ROOF SURFACE PAYMENT FACTOR

The percentage, as indicated in the Roof Surface Payment Schedule, applied to all your roof surface components and installation, including overhead, profit, labor and fees, associated with replacement of your roof surface(s) and based on the age and type of your roof surface components.

L. CONTRACTORS OVERHEAD AND PROFIT

When appropriate, overhead and profit may be included to account for the services of a general contractor.

M. TOTAL WITH TAX

The total estimate with any applicable tax and/or overhead and profit.

LF = Linear Feet **SQ** = 100 Square Feet **SF** = Square Feet **SY** = Square Yard **EA** = Each

*This is a sample guide to your adjuster summary

Allstate Insurance Company, Allstate Indemnity Company, Allstate Fire and Casualty Insurance Company, Allstate Property and Casualty Insurance Company, Northbrook, IL.

©2018 Allstate Insurance Company. allstate.com 09/2018

Allstate. You're in good hands.

Internal Information

N **Summary for Dwelling**
Summary for All Items

Line Item Total		5,348.16
Material Sales Tax	O	29.71
General Contractor Overhead		537.79
General Contractor Profit		537.79
Total Tax		297.49
Replacement Cost Value		$6,750.94
Customer Portion for RPS		(2,048.24)
RPS Value		$4,702.70
Less Depreciation		(78.01)
Actual Cash Value	P	$4,624.69
Less Deductible		(1,000.00)
Net Claim	Q	$3,624.69
Total Recoverable Depreciation	R	78.01
Net Claim if Depreciation is Recovered		$3,702.70

SAMPLE

© Xactware

N. SUMMARY OF INVOLVED COVERAGE
The involved policy coverage for the damaged area.

O. SALES TAX
Based upon where the loss occurred, the sales tax laws may vary by state regarding the application of sales tax to materials and labor.

P. DEDUCTIBLE APPLIED
Reflects the applicable policy deductible applied.

Q. NET CLAIM FOR INVOLVED COVERAGE
The total replacement cost less recoverable and non-recoverable depreciation and any applicable deductible equals the amount of the settlement for the involved coverage.

R. RECOVERABLE DEPRECIATION
Total amount of depreciation that is recoverable. Depending on your policy language, you may be able to recover your depreciation upon your repair or replacement of the depreciated items.

*This is a sample guide to your adjuster summary
Allstate Insurance Company, Allstate Indemnity Company, Allstate Fire and Casualty Insurance Company, Allstate Property and Casualty Insurance Company, Northbrook, IL.
©2018 Allstate Insurance Company. allstate.com 09/2018

Allstate. You're in good hands.

Allstate Insurance Company

P.O. Box 660636
Dallas, TX 75266
Fax: 866-447-4293
www.myclaim.com

EARLINE_COTTRELL

EARLINE_COTTRELL1

Source - EagleView Roof (EARLINE_COTTRELL1) (EARLINE_COTTRELL1) (EARLINE_COTTRELL)

Source - EagleView Roof



Dwelling Roof

5138.44	Surface Area	51.38	Number of Squares
354.19	Total Perimeter Length	75.29	Total Ridge Length
327.18	Total Hip Length		

DESCRIPTION	QUANTITY	UNIT	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
Full Roof Replacement								
1. Remove Laminated - comp. shingle rfg. - w/ felt	51.38 SQ	79.50	4,084.71	0/30 yrs	Avg.	NA	(0.00)	4,084.71
2. Laminated - comp. shingle rfg. - w/out felt	60.00 SQ	282.73	16,963.80	0/30 yrs	Avg.	NA	(0.00)	16,963.80
Auto Calculated Waste: 16.8%, 8.62SQ Options: Valleys: Closed-cut (half laced), Include eave starter course: Yes, Include rake starter course: No, Exposure - Hip/Valley/Starter: 5 5/8", Bundle Rounding: 0.6%, 0.32SQ - (included in waste calculation above) This line item includes an allowance of $121.14 per unit, which reflects current market values in your area. Market prices were verified by Material Supply Warehouse (MSW). While you or your contractor are under no obligation to use this supplier, MSW allows you or your contractor of choice to have materials delivered to your home for installation. For more information on MSW, please visit www.materialsupplywarehouse.com, or contact them at info@materialsupplywarehouse.com, or 888-508-5009.								
3. Roofing felt - 15 lb.	51.38 SQ	41.10	2,111.72	0/20 yrs	Avg.	NA	(0.00)	2,111.72
4. Hip / Ridge cap - Standard profile - composition shingles	403.00 LF	6.99	2,816.97	0/30 yrs	Avg.	NA	(0.00)	2,816.97
5. Drip edge	354.19 LF	3.18	1,126.32	0/35 yrs	Avg.	NA	(0.00)	1,126.32
Roof Components								
6. Roof vent - turtle type - Metal	6.00 EA	79.49	476.94	0/35 yrs	Avg.	NA	(0.00)	476.94
7. Flashing - pipe jack	3.00 EA	60.02	180.06	0/35 yrs	Avg.	NA	(0.00)	180.06
8. Digital satellite system - Detach & reset	1.50 EA	50.29	75.44	0/NA	Avg.	NA	(0.00)	75.44
9. R&R Valley metal - (W) profile	171.00 LF	8.74	1,494.54	0/35 yrs	Avg.	NA	(0.00)	1,494.54
10. Continuous ridge vent - shingle-over style	61.33 LF	11.42	700.39	0/35 yrs	Avg.	NA	(0.00)	700.39
Additional Charges								
11. Remove Additional charge for steep roof - 7/12 to 9/12 slope	51.38 SQ	17.76	912.51	0/NA	Avg.	NA	(0.00)	912.51
12. Additional charge for steep roof - 7/12 to 9/12 slope	51.38 SQ	53.81	2,764.76	0/NA	Avg.	NA	(0.00)	2,764.76
Totals: Dwelling Roof			**33,708.16**				**0.00**	**33,708.16**

Front Elevation

DESCRIPTION	QUANTITY	UNIT	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
13. R&R Downspout - aluminum - 6"*	12.00 LF	14.93	179.16	0/25 yrs	Avg.	0%	(0.00)	179.16

Allstate Insurance Company

P.O. Box 660636
Dallas, TX 75266
Fax: 866-447-4293
www.myclaim.com

CONTINUED - Front Elevation

DESCRIPTION	QUANTITY	UNIT	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
Totals: Front Elevation			**179.16**				**0.00**	**179.16**

Right Elevation

DESCRIPTION	QUANTITY	UNIT	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
No storm related damages								
Totals: Right Elevation			**0.00**				**0.00**	**0.00**

Back Elevation

DESCRIPTION	QUANTITY	UNIT	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
No storm related damages								
Totals: Back Elevation			**0.00**				**0.00**	**0.00**

Left Elevation

DESCRIPTION	QUANTITY	UNIT	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
No storm related damages								
Totals: Left Elevation			**0.00**				**0.00**	**0.00**

Temporary Repairs

DESCRIPTION	QUANTITY	UNIT	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
14. R&R Tarp - all-purpose poly - per sq ft (labor and material)	3.00 SF	1.35	4.05	0/NA	Avg.	0%	(0.00)	4.05
Totals: Temporary Repairs			**4.05**				**0.00**	**4.05**

Allstate Insurance Company

P.O. Box 660636
Dallas, TX 75266
Fax: 866-447-4293
www.myclaim.com

Dwelling - Interiors



Garage — Height: 8'

554.00	SF Walls	520.00	SF Ceiling
1074.00	SF Walls & Ceiling	520.00	SF Floor
57.78	SY Flooring	69.00	LF Floor Perimeter
92.00	LF Ceil. Perimeter		

Door	**7' X 6' 8"**	**Opens into Exterior**
Door	**14' X 7'**	**Opens into Exterior**
Door	**2' X 6' 8"**	**Opens into Exterior**
Window	**2' X 4'**	**Opens into Exterior**
Window	**2' X 4'**	**Opens into Exterior**
Window	**2' X 4'**	**Opens into Exterior**

DESCRIPTION	QUANTITY	UNIT	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
Long term damages								
Totals: Garage			**0.00**				**0.00**	**0.00**



Basement — Height: 8'

557.33	SF Walls	366.00	SF Ceiling
923.33	SF Walls & Ceiling	334.00	SF Floor
37.11	SY Flooring	64.33	LF Floor Perimeter
94.00	LF Ceil. Perimeter		

Missing Wall - Goes to Floor	**9' X 6' 8"**	**Opens into Exterior**
Missing Wall - Goes to Floor	**7' X 6' 8"**	**Opens into Exterior**
Door	**3' X 6' 8"**	**Opens into Exterior**
Window	**3' X 4'**	**Opens into Exterior**
Window	**6' X 4'**	**Opens into Exterior**

DESCRIPTION	QUANTITY	UNIT	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
Long term damages								
Totals: Basement			**0.00**				**0.00**	**0.00**

Allstate Insurance Company

P.O. Box 660636
Dallas, TX 75266
Fax: 866-447-4293
www.myclaim.com



Bathroom — Height: Attic

393.64	SF Walls	154.32	SF Ceiling
547.97	SF Walls & Ceiling	109.19	SF Floor
12.13	SY Flooring	32.50	LF Floor Perimeter
57.13	LF Ceil. Perimeter		

Window	**3' X 4'**	**Opens into Exterior**
Door	**3' X 6' 8"**	**Opens into Exterior**
Door	**3' X 6' 8"**	**Opens into Exterior**

DESCRIPTION	QUANTITY	UNIT	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
Long term damages								
Totals: Bathroom			**0.00**				**0.00**	**0.00**



Bedroom — Height: Attic

541.24	SF Walls	273.72	SF Ceiling
814.96	SF Walls & Ceiling	233.96	SF Floor
26.00	SY Flooring	54.99	LF Floor Perimeter
73.22	LF Ceil. Perimeter		

Door	**3' X 6' 8"**	**Opens into Exterior**
Window	**2' X 4'**	**Opens into Exterior**
Door	**3' X 6' 8"**	**Opens into Exterior**
Door	**3' X 6' 8"**	**Opens into Exterior**
Window	**2' X 4'**	**Opens into Exterior**

DESCRIPTION	QUANTITY	UNIT	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
Long term damages								
Totals: Bedroom			**0.00**				**0.00**	**0.00**

Allstate Insurance Company

P.O. Box 660636
Dallas, TX 75266
Fax: 866-447-4293
www.myclaim.com



Kitchen

Height: Attic

225.89	SF Walls	279.33	SF Ceiling
505.22	SF Walls & Ceiling	229.33	SF Floor
25.48	SY Flooring	18.08	LF Floor Perimeter
70.56	LF Ceil. Perimeter		

Missing Wall - Goes to Floor	**7' X 6' 8"**	**Opens into Exterior**
Door	**3' X 6' 8"**	**Opens into Exterior**
Missing Wall - Goes to Floor	**13' X 9'**	**Opens into Exterior**
Window	**2' X 4'**	**Opens into Exterior**
Window	**2' X 4'**	**Opens into Exterior**
Window	**2' X 4'**	**Opens into Exterior**

DESCRIPTION	QUANTITY	UNIT	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
Long term damages								
Totals: Kitchen			**0.00**				**0.00**	**0.00**

Debris

DESCRIPTION	QUANTITY	UNIT	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
15. Haul debris - per pickup truck load - including dump fees	0.25 EA	198.09	49.52	0/NA	Avg.	NA	(0.00)	49.52
Totals: Debris			**49.52**				**0.00**	**49.52**
Total: Source - EagleView Roof			**33,940.89**				**0.00**	**33,940.89**
Total: Source - EagleView Roof (EARLINE_COTTRELL1) (EARLINE_COTTRELL1) (EARLINE_COTTRELL)			**33,940.89**				**0.00**	**33,940.89**
Total: EARLINE_COTTRELL1			**33,940.89**				**0.00**	**33,940.89**
Line Item Totals: EARLINE_COTTRELL			**33,940.89**				**0.00**	**33,940.89**

[%] - Indicates that depreciate by percent was used for this item

[M] - Indicates that the depreciation percentage was limited by the maximum allowable depreciation for this item

P.O. Box 660636
Dallas, TX 75266
Fax: 866-447-4293
www.myclaim.com

Grand Total Areas:

2,272.11	SF Walls	1,593.37	SF Ceiling	3,865.49	SF Walls and Ceiling
1,426.48	SF Floor	158.50	SY Flooring	238.90	LF Floor Perimeter
0.00	SF Long Wall	0.00	SF Short Wall	386.91	LF Ceil. Perimeter
1,426.48	Floor Area	1,660.25	Total Area	2,272.11	Interior Wall Area
3,398.69	Exterior Wall Area	389.78	Exterior Perimeter of Walls		
5,138.44	Surface Area	51.38	Number of Squares	354.19	Total Perimeter Length
75.29	Total Ridge Length	327.18	Total Hip Length		

Allstate Insurance Company

P.O. Box 660636
Dallas, TX 75266
Fax: 866-447-4293
www.myclaim.com

Factor Detail

AA-Dwelling

Part 1 - Roof Surface Payment Schedule (RPS)

Description	RPS Factor	Quantity	Unit	Unit Price	Total	RPS Total
EARLINE_COTTRELL1 - Source - EagleView Roof (EARLINE_COTTRELL1) (EARLINE_COTTRELL1) (EARLINE_ COTTRELL) - Source - EagleView Roof - Dwelling Roof						
2. Laminated - comp. shingle rfg. - w/out felt	37%	60.00	SQ	282.73	16,963.80	6,276.61
Auto Calculated Waste: 16.8%, 8.62SQ Options: Valleys: Closed-cut (half laced), Include eave starter course: Yes, Include rake starter course: No, Exposure - Hip/Valley/Starter: 5 5/8", Bundle Rounding: 0.6%, 0.32SQ - (included in waste calculation above)						
This line item includes an allowance of $121.14 per unit, which reflects current market values in your area. Market prices were verified by Material Supply Warehouse (MSW). While you or your contractor are under no obligation to use this supplier, MSW allows you or your contractor of choice to have materials delivered to your home for installation. For more information on MSW, please visit www.materialsupplywarehouse.com, or contact them at info@materialsupplywarehouse.com, or 888-508-5009.						
3. Roofing felt - 15 lb.	37%	51.38	SQ	41.10	2,111.72	781.34
4. Hip / Ridge cap - Standard profile - composition shingles	37%	403.00	LF	6.99	2,816.97	1,042.28
5. Drip edge	37%	354.19	LF	3.18	1,126.32	416.74
6. Roof vent - turtle type - Metal	37%	6.00	EA	79.49	476.94	176.47
7. Flashing - pipe jack	37%	3.00	EA	60.02	180.06	66.62
8. Digital satellite system - Detach & reset	37%	1.50	EA	50.29	75.44	27.91
9a. Remove Valley metal - (W) profile	N/A	171.00	LF	0.80	136.80	136.80
9b. Valley metal - (W) profile	37%	171.00	LF	7.94	1,357.74	502.36
10. Continuous ridge vent - shingle-over style	37%	61.33	LF	11.42	700.39	259.14
12. Additional charge for steep roof - 7/12 to 9/12 slope	37%	51.38	SQ	53.81	2,764.76	1,022.96
Subtotal: EARLINE_COTTRELL1 - Source - EagleView Roof (EARLINE_COTTRELL1) (EARLINE_COTTRELL1) (EARLINE_COTTRELL) - Source - EagleView Roof - Dwelling Roof					**$28,710.94**	**$10,709.23**

Line Item Total	**$28,710.94**	**$10,709.23**
Material Sales Tax	857.87	317.41
Replacement Cost Value	**$29,568.81**	
RPS Value		**$11,026.64**

Part 2 - Unfactored Items

Description	Quantity	Unit	Unit Price	RCV	Depreciation	ACV
EARLINE_COTTRELL1 - Source - EagleView Roof (EARLINE_COTTRELL1) (EARLINE_COTTRELL1) (EARLINE_ COTTRELL) - Source - EagleView Roof - Dwelling Roof						

Allstate Insurance Company

P.O. Box 660636
Dallas, TX 75266
Fax: 866-447-4293
www.myclaim.com

Description	Quantity	Unit	Unit Price	RCV	Depreciation	ACV
Full Roof Replacement						
1. Remove Laminated - comp. shingle rfg. - w/ felt	51.38	SQ	79.50	4,084.71	0.00	4084.71
Roof Components						
Additional Charges						
11. Remove Additional charge for steep roof - 7/12 to 9/12 slope	51.38	SQ	17.76	912.51	0.00	912.51
Subtotal: EARLINE_COTTRELL1 - Source - EagleView Roof (EARLINE_COTTRELL1) (EARLINE_COTTRELL1) (EARLINE_ COTTRELL) - Source - EagleView Roof - Dwelling Roof				**$4,997.22**	**$0.00**	
EARLINE_COTTRELL1 - Source - EagleView Roof (EARLINE_COTTRELL1) (EARLINE_COTTRELL1) (EARLINE_ COTTRELL) - Source - EagleView Roof - Front Elevation						
13a. Remove Downspout - aluminum - 6"	12.00	LF	0.69	8.28	0.00	8.28
13b. Downspout - aluminum - 6"	12.00	LF	14.24	170.88	0.00	170.88
Subtotal: EARLINE_COTTRELL1 - Source - EagleView Roof (EARLINE_COTTRELL1) (EARLINE_COTTRELL1) (EARLINE_ COTTRELL) - Source - EagleView Roof - Front Elevation				**$179.16**	**$0.00**	
EARLINE_COTTRELL1 - Source - EagleView Roof (EARLINE_COTTRELL1) (EARLINE_COTTRELL1) (EARLINE_ COTTRELL) - Source - EagleView Roof - Temporary Repairs						
14a. Remove Tarp - all-purpose poly - per sq ft (labor and material)	3.00	SF	0.11	0.33	0.00	0.33
14b. Tarp - all-purpose poly - per sq ft (labor and material)	3.00	SF	1.24	3.72	0.00	3.72
Subtotal: EARLINE_COTTRELL1 - Source - EagleView Roof (EARLINE_COTTRELL1) (EARLINE_COTTRELL1) (EARLINE_ COTTRELL) - Source - EagleView Roof - Temporary Repairs				**$4.05**	**$0.00**	
EARLINE_COTTRELL1 - Source - EagleView Roof (EARLINE_COTTRELL1) (EARLINE_COTTRELL1) (EARLINE_ COTTRELL) - Source - EagleView Roof - Debris						
15. Haul debris - per pickup truck load - including dump fees	0.25	EA	198.09	49.52	0.00	49.52
Subtotal: EARLINE_COTTRELL1 - Source - EagleView Roof (EARLINE_COTTRELL1) (EARLINE_COTTRELL1) (EARLINE_ COTTRELL) - Source - EagleView Roof - Debris				**$49.52**	**$0.00**	
Subtotal				**$5,229.95**	**$0.00**	
Material Sales Tax				8.05	0.00	
Replacement Cost Value				**$5,238.00**		
Less Non-recoverable Depreciation					<0.00>	
Actual Cash Value						**$5,238.00**

Allstate Insurance Company

P.O. Box 660636
Dallas, TX 75266
Fax: 866-447-4293
www.myclaim.com

Summary for
AA-Dwelling

Summary for Roof Surface Payment Schedule (RPS)

Line Item Total	**$28,710.94**
Material Sales Tax	857.87
Replacement Cost Value	**$29,568.81**
Customer Portion for RPS	(18,542.17)
RPS Value	**$11,026.64**

Summary for Unfactored Items

Line Item Total	**$5,229.95**
Material Sales Tax	8.05
Replacement Cost Value	**$5,238.00**
Less Non-recoverable Depreciation	<0.00>
Actual Cash Value	**$5,238.00**

Summary for All Items

Line Item Total	33,940.89
Material Sales Tax	865.92
Replacement Cost Value	**$34,806.81**
Customer Portion for RPS	(18,542.17)
RPS Value	**$16,264.64**
Less Non-recoverable Depreciation	<0.00>
Actual Cash Value	**$16,264.64**
Less Deductible	(2,500.00)
Net Claim	**$13,764.64**

Tyler Palmer

Allstate Insurance Company

P.O. Box 660636
Dallas, TX 75266
Fax: 866-447-4293
www.myclaim.com

Recap of Taxes

	Material Tax (0%)	Material Sales Tax (8%)	Cln Matl Tax (8%)	Cln&Carpet Svc Tax (8%)
Line Items	0.00	865.92	0.00	0.00
Total	**0.00**	**865.92**	**0.00**	**0.00**

Allstate Insurance Company

P.O. Box 660636
Dallas, TX 75266
Fax: 866-447-4293
www.myclaim.com

Depending upon the circumstances of your loss, our estimate may or may not include an amount for general contractor's overhead and profit. If you have questions regarding general contractor's overhead and profit and whether the services of a general contractor are appropriate for your loss, please contact your claim representative before proceeding with repairs.

Any person who, with intent to defraud or knowing that he is facilitating a fraud against an insurer, submits an application or files a claim containing a false or deceptive statement is guilty of insurance fraud.

This document includes a damage estimate for your property based on Replacement Cost Value (RCV) and Actual Cash Value (ACV). The ACV estimate reflects the RCV less the amount of any depreciation. Depreciation is the decrease in value of an item due to the item's condition, which takes into consideration age, life expectancy, usage, type of item, and market factors. As your adjuster has explained, depending on your policy, you may be able to recover your depreciation upon your repair or replacement of the covered damages.

During the claim process, we asked for your assistance in establishing the age and condition of your damaged items. If you have any questions regarding the age and condition applied to your property, or any other questions regarding this estimate, please contact your adjuster.

Specialized skill, licensing or certification may be needed of any contractor(s) that you retain, for instance, to identify the presence and nature of any potential contaminants, toxins, pollutants, or other hazards that may be encountered during the course of the work, or to utilize appropriate work practices and procedures during the course of the work. Check with your local or State public health or environmental agency regarding potential hazards, including contractor qualifications and other requirements. For your safety, it is prudent to avoid areas where damaged structures, materials or unknown substances may be present, and to not disturb such structures, material, or unknown substances until your contractors have inspected the work site.

The suggestions above are provided only for your consideration. They in no way supplement, alter or modify your existing coverage. Your insurance policy is the legal contract that contains the terms and limitations of your coverage.

If you have any concerns about the grade of flooring on your estimate, you may take advantage of a free service that will provide you with a more specific analysis. To use this option, please keep a 12" x 12" sample of your damaged flooring, and notify your Allstate adjuster that you would like the additional analysis.