Complications & Workarounds

- Jaguar Print, Making Spaghetti
- Cube Prints, Z axis bind, keynote image
- Cat, Pig, Puppy
- Print Bed Leveling issues
- Frame and Table leveling issues
- Other failed prints

Digital Files

- 2cm Cube Low Quality
- 2cm Cube Med Quality
- 2cm Cube Ultra Quality
- 2cm Cube Concentric Top/Bottom
- 2cm Tube Single Extrusion
- 2cm Tube Double Extrusion, Random Z axis
- 2cm Cylinder .1cm Tolerance w/ supports
- 2cm Cylinder .005cm Tolerance
- 20mm Cube with 5mm hole



3dm STL Gcode



3dm STL Gcode

3dm STL