
4/15/2025


working on housing refinements

* need to make LED acray hole smaller, move up by 3 mm

* need to redo LED hole, it's an oval not a circle




* need to redo button hole for new button



* need to lengthen screen holes

* med to make cotacy encoder more shallow maybe



* need to rework PCB power hole


inner edge of hole to edge of the adapter

4/18/2025

A button hole




* power hole



* PCB boilts





back view