

Royal Auto Garage

Plot 14, Industrial Estate, Near Highway Junction | GSTIN: 27ABCDE1234F1Z5

TAX INVOICE

Invoice No: INV-2026-8630
Invoice Date: 23/01/2026
Customer Name: Meera Sharma
Vehicle No: WB 41 CA 4831
Make / Model: Hyundai i20

S.No	Description	Qty	Rate	Amount
1	Tail Lamp Assembly	1	2,750.00	2,750.00
2	Rear Bumper Repair	1	2,400.00	2,400.00
3	Labour Charges	1	3,100.00	3,100.00
4	Windshield Glass	1	14,150.00	14,150.00
Sub Total				22,400.00
CGST @ 9%				2,016.00
SGST @ 9%				2,016.00
Grand Total				44,200.00