

Prime Wheels Workshop

Plot 14, Industrial Estate, Near Highway Junction | GSTIN: 27ABCDE1234F1Z5

TAX INVOICE

Invoice No: INV-2026-1624
Invoice Date: 28/01/2026
Customer Name: Anjali Nair
Vehicle No: RJ 08 EH 4155
Make / Model: Maruti Suzuki Swift

S.No	Description	Qty	Rate	Amount
1	Front Bumper Replacement	1	7,250.00	7,250.00
2	Labour Charges	1	2,750.00	2,750.00
3	Side Mirror Assembly	1	3,950.00	3,950.00
4	Rear Bumper Repair	1	3,500.00	3,500.00
5	Headlamp Assembly (LH)	1	6,300.00	6,300.00
Sub Total				23,750.00
CGST @ 9%				2,137.50
SGST @ 9%				2,137.50
Grand Total				28,025.00