Engineering Change Notice: Seal Upgrade for HX-200 Pumps

Document No: ECN-0412 Revision: A Date: 2025-03-18

Reason for change

Repeat seal failures on Pump P-204 (INC-2024-078) caused by operation at 105 deg C against a 90 deg C seal limit.

Change description

Replace carbon vs silicon carbide seal faces with silicon carbide vs silicon carbide faces. Raise the rated maximum process temperature of the HX-200 from 90 deg C to 120 deg C.

Affected documents

Document	Current revision	Action
MAN-HX200-001	B	Update to Revision C
MP-17 Seal Replacement Procedure	A	Update to Revision B
Drawing DWG-HX200-SEAL	D	No change

Approval

Approved by Reliability Manager, 2025-03-18. Implementation target: next planned shutdown.