Pump P-204 Maintenance History

Document No: MNT-P204-LOG Revision: A Date: 2025-12-01

Work order history

WO number	Date	Activity	Findings
WO-20871	2022-09-10	Grease replacement	Grease dark, normal wear
WO-21544	2023-04-22	Seal inspection	Carbon face wear within limits
WO-22310	2024-02-15	Seal replacement	Seal leaking, carbon faces worn, replaced with same type
WO-22977	2024-11-03	Seal replacement	Repeat leakage after 8 months, faces cracked
WO-23650	2025-06-20	Seal upgrade per ECN-0412	Installed silicon carbide faces, manual Rev C applied
WO-24102	2025-10-12	Bearing inspection	Vibration 3.1 mm/s, acceptable

Note: process temperature was raised from 85 deg C to 105 deg C in January 2024 for a production rate increase. Revision B of the manual (limit 90 deg C) was still in use until June 2025.