
		HOJA DE PROCESO.	Proceso 1/95 para 1 piezas		Hoja Nº1 de 1
Conjunto		Práctica TP-1	Material	3	F-1140
Plano	3	T-10	Dimens. en bruto	::	Ø50 x 82
Realizado Fecha	* * *		Comprobado Fecha	Same.	



ta. Control	Pasada	Vel. Corte	Avance	Dimensión		Tiempo		
n control	n p	m/m rpm	mm/m/x	ď	1	Máq.	Man.	Pre
f1 Pie-Rey f1 Pie-rey f1 Pie-Rey f1 Pie-Rey f1 Pie-Rey f1 Pie-Rey f3	2 0.75 1 0.5 1 0.5 1 0.5 6 1.8 1 0.5	5 135 86 5 110 70 5 135 86 8 110 70 5 135 86	00 0.10 00 0.15 00 0.10 00 —	50	25 25 52 52 44.1 21	0.17 0.19		
74 Pie-Rey	1 5.12			10.25	33	8		
16 :	3	50000 50000		12	20	9		
1 Pie-Rey 1 Pie-rey 1 Pie-rey 1 Pie-rey 2		135	0.15 0.10 0.15 0.15) (525
ra .			Pie-rey 135	Pie-rey 135 0.10	Pie-rey 135 0.10	Pie-rey 135 0.10	Pie-rey 135 0.10	Pie-rey 135 0.10