Bode Diagram Gm = Inf dB (at Inf rad/s), Pm = 141 deg (at 0.706 rad/s)50 Magnitude (dB) -50-100 90 Phase (deg) -90-18010⁰ 10¹

Frequency (rad/s)