



General Details

Assessor	Samuel Prieto Ayllon
Assessment Date	02/07/2025
Assigned Reviewer	Samuel Prieto Ayllon
Next Review Date	02/07/2026

Signed Off By	Oraib AlKheetanRojas
Signed Off On	19/05/2026
Sign Off Comments	

Operation Assessed	Thermal/Visible Camera – Workswell WIRIS Pro Operation
--------------------	--

Associated with specific area

-  Basement 2
-  B2 029 (Robotics Lab)
-  CTP

Description of work area and/or activity assessed

The Workswell WIRIS Pro is a combined thermal-imaging and visible-light camera that mounts on drones or tripods to capture radiometric data and HD video for research inspections. Typical use involves bench setup in the Robotics Lab for configuration, followed by indoor or outdoor drone flights where the unit is powered via a 9-36 V DC lead and streams HDMI video to a ground station.

Reason for Risk Assessment

To document and control any health, safety, and equipment-damage risks introduced by actively using the WIRIS Pro in research activities.

Overall Current Risk

Low Risk



Average Number of Persons Affected

2	 Employees
2	 Students

Current Rating	Hazard Information	Task Status
Low Risk 	Electricity The camera is powered from an external 9-36 V DC supply; exposed conductors or damaged insulation could cause a mild electric shock, short-circuit, or spark during installation, relocation, or maintenance.	0 0 0
	Measures Currently in place to prevent risk of injury	
	Power input limited to Safety Extra-Low Voltage (SELV) and polarity-keyed barrel connector. Switch or injector kept de-energised until the DC lead is fully connected (“power-on last” rule). All cables routed and strain-relieved; periodic visual inspection of insulation and connectors. Operators trained in safe connection and disconnection procedures.	

Potential Rating	Additional Controls Required
Low Risk 	No Remedial Actions Entered If there are any reasonably practicable actions which can be taken to reduce the risk associated with this hazard please use the form above to enter them.

Current Rating	Hazard Information	Task Status
Low Risk 	Hot surfaces Internal electronics and the infrared sensor warm during operation; surface temperatures can approach 50 °C, risking minor burns on prolonged contact and degrading optics if touched while hot.	0 0 0
	Measures Currently in place to prevent risk of injury	
	Allow 15 minutes post-power-down before handling lens housing. Use the supplied focus tool when adjustments are required.	

Potential Rating	Additional Controls Required
Low Risk 	No Remedial Actions Entered If there are any reasonably practicable actions which can be taken to reduce the risk associated with this hazard please use the form above to enter them.

Current Rating	Hazard Information	Task Status
Low Risk 	Fall of Object from Height When drone-mounted, mechanical failure of the ¼-20 UNC attachment or drone crash could drop the 430 g camera from height, causing injury to bystanders or damage to equipment.	0 0 0
	Measures Currently in place to prevent risk of injury	
	Mounting screw torqued to manufacturer specification; inspected before every flight. Flight zone secured with 5 m exclusion radius and overhead hazard warnings. Operations restricted to licensed pilots.	

Potential Rating	Additional Controls Required
Low Risk 	No Remedial Actions Entered If there are any reasonably practicable actions which can be taken to reduce the risk associated with this hazard please use the form above to enter them.

