



General Details

Assessor	Samuel Prieto Ayllon
Assessment Date	03/07/2025
Assigned Reviewer	Samuel Prieto Ayllon
Next Review Date	03/07/2026

Signed Off By	Oraib AlKheetanRojas
Signed Off On	19/05/2026
Sign Off Comments	

Operation Assessed	Event Camera – Prophesee Metavision EVK4-HD Operation
--------------------	---

Associated with specific area

-  Basement 2
-  B2 029 (Robotics Lab)
-  CTP

Description of work area and/or activity assessed

This assessment covers routine use of the Prophesee Metavision EVK4-HD event-based vision camera for research. The device is powered over USB 3.0 Type-C, controlled via Metavision Intelligence software, and typically mounted on a tripod or robot for data capture and relocation within the lab.

Reason for Risk Assessment

To document and control any health, safety, and equipment-damage risks introduced by actively using the EVK4-HD in research activities.

Overall Current Risk

Low Risk



Average Number of Persons Affected

2	 Employees
2	 Students
2	 Visitors

Current Rating	Hazard Information	Task Status
Low Risk	⚠️ Electricity Contact with or damage to the 5 V SELV USB-C lead could cause minor electric shock, short-circuit, or sparking when operators connect, disconnect, or move the camera. The cable also energises synchronisation pins that expose 3.3 V logic if mis-wired.	0 0 0
	Measures Currently in place to prevent risk of injury	
	• USB power is limited to SELV from the host PC or a certified hub. • Follow “power-on last, power-off first” practice when connecting or removing the cable. • Use only intact, strain-relieved USB-C leads fixed with the camera’s threaded retention holes to prevent accidental pull-out • Visual inspection of connectors and insulation before each use. • Operators trained in safe handling of computer-peripheral cables.	

Potential Rating	Additional Controls Required
Low Risk	No Remedial Actions Entered If there are any reasonably practicable actions which can be taken to reduce the risk associated with this hazard please use the form above to enter them.

Current Rating	Hazard Information	Task Status
Low Risk	⚠️ Fall of Object from Height The camera (~ 40 g) is often secured to a tripod, UAV or robot mast; loose mounting screws or accidental knocks could let the unit or attached lens fall, potentially striking people or damaging equipment. The body provides multiple M2/M2.6 mounts and a standard tripod screw	0 0 0
	Measures Currently in place to prevent risk of injury	
	• Always fasten the tripod screw or robot bracket to the specified torque. • Use all provided mounting points where possible and verify engagement before powering the system. • Keep lens caps on during installation, and avoid overhead mounting above head height. • Relocate the setup away from walkways when recording.	

Potential Rating	Additional Controls Required
Low Risk	No Remedial Actions Entered If there are any reasonably practicable actions which can be taken to reduce the risk associated with this hazard please use the form above to enter them.