



General Details

Assessor	Samuel Prieto Ayllon
Assessment Date	30/06/2025
Assigned Reviewer	Samuel Prieto Ayllon
Next Review Date	30/06/2026

Signed Off By	Oraib AlKheetanRojas
Signed Off On	19/05/2026
Sign Off Comments	

Operation Assessed	Routine operation of a FARO Focus S 350 Plus terrestrial laser scanner
--------------------	--

Associated with specific area

 Basement 2

 B2 029 (Robotics Lab)

 CTP

Description of work area and/or activity assessed

This document describes the typical risks associated with the operation of the 3D scanner in both indoor and outdoor scenarios. Users place the Focus S 350 Plus on a tripod, power it from an on-board Li-ion battery or the AC adapter, and perform $360 \times 300^\circ$ phase-shift laser scans. Typical tasks include battery charging, SD-card handling, transporting the unit to/from site and cleaning optics.

Reason for Risk Assessment

To document and control any health, safety, and equipment-damage risks introduced by actively using the FARO Focus S 350 Plus terrestrial laser scanner in active research.

Overall Current Risk

Low Risk



Average Number of Persons Affected

2  Employees

2  Students

Current Rating	Hazard Information	Task Status
Low Risk	Electricity Dangerously high voltages are present inside the enclosure. Only qualified service personnel should open the housing. Never push objects of any kind into this product through openings, as they may touch dangerous voltage points or cause short circuits. This could result in a fire, electric shock, or damage to the product.	0 0 0
	Measures Currently in place to prevent risk of injury	
	The device is charged only on FARO PowerDock in clear ventilated areas The product is operated only from the power source or the supplied battery Visual inspection of connectors and insulation before usage Operator trained in the proper use of the equipment	

Potential Rating	Additional Controls Required
Low Risk	No Remedial Actions Entered If there are any reasonably practicable actions which can be taken to reduce the risk associated with this hazard please use the form above to enter them.

Current Rating	Hazard Information	Task Status
Low Risk	Moving Parts The mirror unit rotates with high speed while scanning and for a short period after the scan. While the mirror is rotating keep distance to the product and do not touch the rotating mirror unit with your hands, fingers or any objects at the risk of personal injury and damage to the FARO Laser Scanner.	0 0 0
	Measures Currently in place to prevent risk of injury	
	The scanner is only used when set on a flat and stable surface Ensure that the scanner head can rotate freely and will not hit any objects during the scan The user keeps a 0.5 m exclusion zone around the scanner when in use Never reach into mirror cavity while powered	

Potential Rating	Additional Controls Required
Low Risk	No Remedial Actions Entered If there are any reasonably practicable actions which can be taken to reduce the risk associated with this hazard please use the form above to enter them.