



SIGN-OFF REQUIRED

This assessment must be digitally signed off by an Authorised User.

General Details

Assessor	Samuel Prieto Ayllon
Assessment Date	30/07/2025
Assigned Reviewer	Samuel Prieto Ayllon
Next Review Date	30/07/2026

Assigned user to Sign Off	Oraib AlKheetanRojas
Signed Off By	This assessment has not yet been signed off
Signed Off On	--
Sign Off Comments	

Operation Assessed	Showcase of quadruped robot at events
--------------------	---------------------------------------

Description of work area and/or activity assessed
This RA (Risk Assessment) pertains to the demonstration activities of Quadruped Robots intended for Community Engagement and Promotional Activities at both internal (NYUAD) and external public events, such as Learning Festivals, Competitions, Hackathons, Conferences, Celebrations, Exhibitions, Shows and more.
Reason for Risk Assessment
To predict and avoid any potential risks during the operation of the robot.

Associated with specific area

-  Basement 2
-  B2 029 (Robotics Lab)
-  CTP

Overall Current Risk

Moderate Risk



Average Number of Persons Affected

2	 Children
2	 Machine Operators
10	 Members of the Public
10	 Visitors

Current Rating	Hazard Information	Task Status
Moderate Risk	Moving Parts - Loss of stability and falls Spot stands up and keeps balancing only with active control. However, active control does not ensure that stable balancing is always attained. - Pinch points during motion Pinch points are present around the joints and legs (see Pinch points) and cannot be entirely eliminated without compromising the mobility of the legs, or the ability to walk and maintain balance. Spot pinch points are situated in areas that are not normally reached in situations other than handling and transportation (while Spot is powered off). When motors are active, there is no foreseeable use that would require access to legs and joints. - Hazards associated with stopping or other powerless motion Spot will automatically disable motor power in the following cases: • As a result of a detected failure or a detected fall. • As a result of a safety-related stopping function forcing a de-energized state.	0 0 1
Measures Currently in place to prevent risk of injury		
Operator user credentials interlock Hardware Emergency switch Software Emergency switch (Soft) Software Emergency switch (Soft) Sensors to proximity from humans and objects		

Potential Rating	Additional Controls Required								
Low Risk	<table><tr><th>Additional Controls and Actions</th><th>Due by / Whom</th><th>Action Status</th></tr><tr><td> Operators should be trained in the use of the robots. Operators should experienced in the use of the robots. Operators will not navigate at high speeds Operators will constantly remind the public to not approach the robots. Operators will monitor the robots for signs of abnormal operation. </td><td> 30/07/2025 S.Prieto Ayllon </td><td> Complete </td></tr></table>	Additional Controls and Actions	Due by / Whom	Action Status	Operators should be trained in the use of the robots. Operators should experienced in the use of the robots. Operators will not navigate at high speeds Operators will constantly remind the public to not approach the robots. Operators will monitor the robots for signs of abnormal operation.	30/07/2025 S.Prieto Ayllon	Complete		
Additional Controls and Actions	Due by / Whom	Action Status							
Operators should be trained in the use of the robots. Operators should experienced in the use of the robots. Operators will not navigate at high speeds Operators will constantly remind the public to not approach the robots. Operators will monitor the robots for signs of abnormal operation.	30/07/2025 S.Prieto Ayllon	Complete							

Current Rating	Hazard Information	Task Status
Low Risk	Fire - Fire, explosion and hazardous materials There are no known significant risks associated with Spot's lubricants. The battery pack contains cells that have electrolytes. All cells are fully enclosed in a sealed enclosure that has passed UN 38.3 transportation testing. In addition, the pack has CB Certification to IEC 62133 and has passed drop testing with no leakage of electrolyte.	0 0 1
	Measures Currently in place to prevent risk of injury	
	Systems monitoring the status of the robot's operation and alert the user if a function or a component are not working properly or if the measurement values (Temperature, Voltage, Current, etc) are out of range. If there is a problem on the crucial systems of the robots the will "lock" and cannot not operate.	

Potential Rating	Additional Controls Required		
Low Risk	Additional Controls and Actions	Due by / Whom	Action Status
	Operator user training	30/07/2025 S.Prieto Ayllon	Complete

Current Rating	Hazard Information	Task Status
Low Risk	Electricity Spot uses a separated extra low-voltage (SELV) power supply design (<60 VDC), meeting the requirements in IEC 60204-1 for electrical equipment and IEC 62133 for batteries. There are no known significant residual risks associated with shocks, either apparent or as a result of faults. Measures Currently in place to prevent risk of injury IEC 60204-1 for electrical equipment and IEC 62133 for batteries.	0 0 1

Potential Rating	Additional Controls Required		
Low Risk	Additional Controls and Actions	Due by / Whom	Action Status
	Operator user training	30/07/2025 S.Prieto Ayllon	Complete

Current Rating	Hazard Information	Task Status
Moderate Risk 	Manual Handling Moving the robot and associated equipment to and from the event presents manual-handling risks, including musculoskeletal strain from lifting a carrying a 35 kg robot.	0 0 0
	Measures Currently in place to prevent risk of injury	
	- Use of a rated wheeled trolley-flight case. - Keep loads close to body. - No lifting from legs/joints. - Minimum of two trained handlers for the robot; single-person lifts only for light accessories. - Route planned in advance (lift preferred over stairs; clear doorways/obstacles). - Vehicle loading with ramp or tail-lift where available; load secured with ratchet straps.	

Potential Rating	Additional Controls Required
Moderate Risk 	No Remedial Actions Entered If there are any reasonably practicable actions which can be taken to reduce the risk associated with this hazard please use the form above to enter them.

Related Files