



SIGN-OFF REQUIRED

This assessment must be digitally signed off by an Authorised User.

General Details

Assessor	Samuel Prieto Ayllon
Assessment Date	18/05/2026
Assigned Reviewer	Samuel Prieto Ayllon
Next Review Date	18/05/2027

Assigned user to Sign Off	Oraib AlKheetanRojas
Signed Off By	This assessment has not yet been signed off
Signed Off On	--
Sign Off Comments	

Operation Assessed	High-Power Programmable DC Power Supply – Operation
--------------------	---

Associated with specific area

-  Basement 2
-  B2 029 (Robotics Lab)
-  CTP

Description of work area and/or activity assessed

This risk assessment covers the use of high-power programmable DC power supplies, including the B&K Precision PVS10005/PVS series, for laboratory research, testing, equipment operation, and powering devices under test. Activities may include setup, connection of loads, adjustment of voltage/current limits, operation in constant-voltage or constant-current mode, monitoring output, connecting test leads, and disconnecting equipment after use. The equipment may generate high DC voltage and high output power, and must only be used by trained/authorised users in the Kinesis CTP lab.

Reason for Risk Assessment

To identify, assess, and control electrical shock, arc, short-circuit, fire, burn, overheating, equipment-damage, and stored-energy risks associated with the use of high-power programmable DC power supplies during research, testing, and equipment operation in the Kinesis CTP lab.

Overall Current Risk

High Risk



Average Number of Persons Affected

2

 Employees

Current Rating	Hazard Information	Task Status
High Risk	⚠️ Electricity The power supply can produce hazardous DC voltages and high output power. Contact with live output terminals, exposed conductors, damaged leads, incorrectly wired loads, or internal components may result in electric shock, burns, serious injury, or equipment damage.	0 0 0
	Measures Currently in place to prevent risk of injury	
	- Only trained/authorised users may operate the power supply. - Power supply must be connected to a correctly grounded electrical supply. - Output must be switched OFF before connecting or disconnecting loads. - Live terminals and conductors must not be touched when output is enabled. - Loads and wiring must have no accessible live parts where hazardous voltages may be present. - Test leads and insulation must be rated for the maximum voltage/current used. - Damaged equipment, cables, connectors, or terminals must not be used. - Covers must not be removed by users; servicing is by qualified personnel only.	

Potential Rating	Additional Controls Required
High Risk	No Remedial Actions Entered If there are any reasonably practicable actions which can be taken to reduce the risk associated with this hazard please use the form above to enter them.

Current Rating	Hazard Information	Task Status
Moderate Risk	⚠️ Hot surfaces High current, poor connections, overloaded cables, short circuits, or prolonged operation may cause cables, terminals, loads, connectors, or internal components to become hot, creating a burn risk.	0 0 0
	Measures Currently in place to prevent risk of injury	
	- Cables and connectors are selected for the expected current and voltage. - Connections are checked for tightness before use. - Users avoid touching terminals, conductors, loads, or cables during and immediately after high-power operation. - Equipment is monitored for overheating, smell, discoloration, or abnormal behaviour. - Output is switched off and equipment allowed to cool before adjustment or handling. - Any overheated or damaged cable/connector is removed from service.	

Potential Rating	Additional Controls Required
Moderate Risk	No Remedial Actions Entered If there are any reasonably practicable actions which can be taken to reduce the risk associated with this hazard please use the form above to enter them.