



General Details

Assessor	Samuel Prieto Ayllon
Assessment Date	18/05/2026
Assigned Reviewer	Samuel Prieto Ayllon
Next Review Date	18/05/2027

Signed Off By	Oraib AlKheetanRojas
Signed Off On	19/05/2026
Sign Off Comments	

Operation Assessed	Soldering Station
--------------------	-------------------

Associated with specific area

 Basement 2

 B2 029 (Robotics Lab)

 CTP

Description of work area and/or activity assessed

This is a RA related to the use of the Soldering station of the Kinesis CTP lap.

Reason for Risk Assessment

To identify, assess, and control health, safety, fire, burn, fume, electrical, and equipment-damage risks associated with the use of the soldering station in the KINESIS CTP lab, including soldering, desoldering, hot-work handling, use of flux/solder, and safe operation of powered soldering equipment.

Overall Current Risk

Moderate Risk



Average Number of Persons Affected

2

 Employees

Current Rating	Hazard Information	Task Status
Moderate Risk 	Fire The soldering station produce heat. If the probe of the soldering station misplaced or misused, its possible to ignite a fire.	0 0 0
	Measures Currently in place to prevent risk of injury	
	- Usage of a Soldering Station which auto-switches off after a time interval. - All personnel using the soldering station has been properly trained - A fire extinguisher is kept in close range of the soldering station - The soldering area is kept tidy and decluttered while performing soldering/desoldering operations	

Potential Rating	Additional Controls Required
Moderate Risk 	No Remedial Actions Entered If there are any reasonably practicable actions which can be taken to reduce the risk associated with this hazard please use the form above to enter them.

Current Rating	Hazard Information	Task Status
Moderate Risk 	Hot surfaces The Soldering Station probe operates in high temperatures (200-380 Degree Celsius). Users should use the tool as suggested by the manufacturer and hold it in the designed holding area. Also the users should be aware of the surroundings and be cautious with their hand movements when they are holding the soldering iron.	0 0 0
	Measures Currently in place to prevent risk of injury	
	- All personnel using the soldering station has been properly trained - A first aid kit is kept in close distance to the soldering station. - The soldering area is kept tidy and decluttered while performing soldering/desoldering operations	

Potential Rating	Additional Controls Required
Moderate Risk 	No Remedial Actions Entered If there are any reasonably practicable actions which can be taken to reduce the risk associated with this hazard please use the form above to enter them.

Current Rating	Hazard Information	Task Status
Moderate Risk 	Gas/Fumes Soldering can produce fumes from flux, solder, heated residues, and cleaning agents. Exposure may cause irritation to the eyes, nose, throat, and respiratory system, particularly if soldering is carried out for extended periods or without effective local extraction.	0 0 0
	Measures Currently in place to prevent risk of injury	
	- A fume extractor is provided and must be used whenever soldering or desoldering is carried out. The extraction inlet must be positioned close to the soldering point to capture fumes at source. - Soldering is carried out in a suitable, well-ventilated area. - Only trained or authorised users are permitted to use the soldering station. - Work must stop if fumes are not being effectively captured by the extractor. - The work area is kept clear and tidy during soldering activities. - Fume extractor filters are checked and replaced as required.	

Potential Rating	Additional Controls Required
Moderate Risk 	No Remedial Actions Entered If there are any reasonably practicable actions which can be taken to reduce the risk associated with this hazard please use the form above to enter them.