
<b>alma</b> CAM	Act/cube	MsoftBatch	2024-07-10 10:23:56	Cut 1	1/1
-----------------	----------	------------	---------------------	-------	-----

# Cut 1 / 2406000103075#EDC#KAS#1#12140# 10,0 130 235SCRM#0



<b>alma</b> CAM	Act/cube	MsoftBatch	2024-07-10 10:23:56	Cut 1	1/1	
-----------------	----------	------------	---------------------	-------	-----	--

		Х	Υ	Z	8<	Name
1	<x></x>	235	130	10		
2	<y></y>	55	130	10		
3	AMSK-03325901-0003 (Y:2)	55	77	10		
4	AMSK-03325901-0003	25	77	10		
5	AMSK-03325901-0003	25	77	10		
6	AMSK-03325901-0004 (Y:2)	55	35	10		
7	AMSK-03325901-0004	25	35	10		
8	AMSK-03325901-0004	25	35	10		
9	<remnant></remnant>	55	8	10		2406000103075#EDC#KAS#1#12140# 10,0 130 235SCRM#0~1
10	<y></y>	175	130	10		
11	<x></x>	175	107	10		
12	AMSK-03325901-0001	76	107	10		
13	AMSK-03325901-0001	76	107	10		
14	<remnant></remnant>	13	107	10		2406000103075#EDC#KAS#1#12140# 10,0 130 235SCRM#0~2
15	<remnant></remnant>	175	18	10		2406000103075#EDC#KAS#1#12140# 10,0 130 235SCRM#0~3

almaCAM A	Act/cube	MsoftBatch	2024-07-10 10:23:56	Cut 1	1/1
-----------	----------	------------	---------------------	-------	-----

# Cut

Index	Material	Block	Remnant	Multiplicity	Х	Y	Z	
1	21PLSCRM	2406000103075#EDC#KAS#1#12140# 10,0 130 235SCRM#0	Yes	1	235	130	10	1

### Parts

Index	Part	Order	Quantity	Х	Y	Z	Comment
1	AMSK-03325901-0001	M-Soft-Export	2	107	76	10	
2	AMSK-03325901-0003	M-Soft-Export	2	77	25	10	
3	AMSK-03325901-0004	M-Soft-Export	2	35	25	10	

### Remnants


	Х	Y	Z
1	55	8	10


	X	Y	Z
2	13	107	10

	Х	Y	Z
3	175	18	10

**almaCAM** Act/cube MsoftBatch 2024-07-10 10:23:56 Cut 2 1/2

### Cut 2 / 2405000038202#EDC#KAS#1#12140# 30,0 130 149SCRM#0





almaCAM Act/cube	MsoftBatch	2024-07-10 10:23:56	Cut 2	1/1	
------------------	------------	---------------------	-------	-----	--

		Х	Υ	Z	8<	Name
1	<x></x>	149	130	30		
2	<y></y>	35	130	30		
3	AMSK-03325901-0005	35	60	30		
4	AMSK-03325901-0005	35	60	30		
5	<remnant></remnant>	35	0	30		2405000038202#EDC#KAS#1#12140# 30,0 130 149SCRM#0~1
6	<z></z>	107	130	30		
7	<y></y>	107	130	25		
8	AMSK-03325901-0002	107	35	25		
9	AMSK-03325901-0002	107	35	25		
10	AMSK-03325901-0002	107	35	25		
11	<x></x>	107	10	25		
12	AMSK-03325901-0003	77	10	25		
13	<remnant></remnant>	25	10	25		2405000038202#EDC#KAS#1#12140# 30,0 130 149SCRM#0~2
14	<remnant></remnant>	107	130	0		2405000038202#EDC#KAS#1#12140# 30,0 130 149SCRM#0~3
15	<loss></loss>	-3	130	30		

almaCAM A	act/cube	MsoftBatch	2024-07-10 10:23:56	Cut 2	1/1
-----------	----------	------------	---------------------	-------	-----

# Cut

Index	Material	Block	Remnant	Multiplicity	Х	Y	Z	
2	21PLSCRM	2405000038202#EDC#KAS#1#12140# 30,0 130 149SCRM#0	Yes	1	149	130	30	

## Parts

Index	Part	Order	Quantity	Х	Y	Z	Comment
1	AMSK-03325901-0002	M-Soft-Export	3	107	35	25	
2	AMSK-03325901-0003	M-Soft-Export	1	77	25	10	
3	AMSK-03325901-0005	M-Soft-Export	2	60	35	30	

### Remnants


	X	Y	Z
1	35	0	30


	Х	Y	Z
2	25	10	25

	Х	Y	Z
3	107	130	0

**almaCAM** Act/cube MsoftBatch 2024-07-10 10:23:56 Cut 3 1/2

### Cut 3 / 2406000023809#EDC#KAS#1#12140# 30,0 65 250SCRM#0





a	<b>lma</b> CAM	Act/cube	MsoftBatch	2024-07-10 10:23:56	Cut 3	1/1
---	----------------	----------	------------	---------------------	-------	-----

			Х	Υ	Z	8<	Name
1		<z></z>	250	65	30		
2		<x></x>	250	65	25		
3		<y></y>	77	65	25		
4	可	AMSK-03325901-0003 (Z:2)	77	25	25		
5	可	AMSK-03325901-0003	77	25	10		
6		AMSK-03325901-0003	77	25	10		
7		AMSK-03325901-0003 (Z:2)	77	25	25		
8		AMSK-03325901-0003	77	25	10		
9		AMSK-03325901-0003	77	25	10		
10		<remnant></remnant>	77	5	25		2406000023809#EDC#KAS#1#12140# 30,0 65 250SCRM#0~1
11		<y></y>	168	65	25		
12		<x></x>	168	35	25		
13		AMSK-03325901-0002	107	35	25		
14		AMSK-03325901-0004 (Z:2)	25	35	25		
15		AMSK-03325901-0004	25	35	10		
16		AMSK-03325901-0004	25	35	10		
17		<remnant></remnant>	26	35	25		2406000023809#EDC#KAS#1#12140# 30,0 65 250SCRM#0~2
18		<x></x>	168	25	25		
19		AMSK-03325901-0003 (Z:2)	77	25	25		
20		AMSK-03325901-0003	77	25	10		
21		AMSK-03325901-0003	77	25	10		
22		AMSK-03325901-0003 (Z:2)	77	25	25		
23		AMSK-03325901-0003	77	25	10		
24		AMSK-03325901-0003	77	25	10		
25		<remnant></remnant>	4	25	25		2406000023809#EDC#KAS#1#12140# 30,0 65 250SCRM#0~3
26		<remnant></remnant>	250	65	0		2406000023809#EDC#KAS#1#12140# 30,0 65 250SCRM#0~4

almaCAM Act/cube	MsoftBatch	2024-07-10 10:23:56	Cut 3	1/1
------------------	------------	---------------------	-------	-----

# Cut

Index	Material	Block	Remnant	Multiplicity	Х	Υ	Z
3	21PLSCRM	2406000023809#EDC#KAS#1#12140# 30,0 65 250SCRM#0	Yes	1	250	65	30

## Parts

Index	Part	Order	Quantity	Х	Y	Z	Comment
1	AMSK-03325901-0002	M-Soft-Export	1	107	35	25	
2	AMSK-03325901-0003	M-Soft-Export	8	77	25	10	
3	AMSK-03325901-0004	M-Soft-Export	2	35	25	10	

## Remnants

	Х	Y	Z
1	77	5	25

	X	Υ	Z
2	26	35	25

	X	Υ	Z
3	4	25	25

	Х	Y	Z
4	250	65	0

# Summary

Nb cut blocks 3 Parts volume (m³) 0 Remnants volume (m³) 0 Loss volume (m³) 0 Sawing volume (m³) 0 Total volume (m³) 0 Part % 66.22 Remnant % 6.62 Loss % 0
Remnants volume (m³) 0  Loss volume (m³) 0  Sawing volume (m³) 0  Total volume (m³) 0  Part % 66.22  Remnant % 6.62
Loss volume (m³) 0 Sawing volume (m³) 0 Total volume (m³) 0 Part % 66.22 Remnant % 6.62
Sawing volume (m³) 0  Total volume (m³) 0  Part % 66.22  Remnant % 6.62
Total volume (m³) 0  Part % 66.22  Remnant % 6.62
Part % 66.22  Remnant % 6.62
Remnant % 6.62
Loss % 0
Sawing % 27.17
Nb of cuts 31
Nb cut parts 23
Nb of parts 23
Nb of remnants 11
Sawing area (m²) 0.08
Time estimate (s) 65
Cost estimate () 0
Comment