

REPAIRER

Repair facility	Riverside Auto Body
Estimate reference	RAB-88214
Estimate date	2026-08-18
Vehicle	2022 Toyota Camry SE (Dark grey)
VIN	4T1C11AK8NU123456
Claim reference	CLM-2026-0431

ESTIMATE OF REPAIR COSTS

OPERATION	AMOUNT
Rear bumper cover - replace	\$640.00
Rear bumper reinforcement bar - replace	\$310.00
Parking sensor set - replace and calibrate	\$465.00
Refinish rear bumper and blend quarter panels	\$720.00
Labour - 6.5 hours body, 2.0 hours refinish	\$345.00
Parts, paint and sundries subtotal	\$2,480.00
Total estimate	\$2,480.00

This estimate is valid for 30 days. Supplementary work may be identified once panels are removed and must be authorised before it is carried out.