

REPAIRER

Repair facility	Clear Lake Collision
Estimate reference	CLC-3097
Estimate date	2026-08-19
Vehicle	2021 Ford Focus ST-Line (Silver)
VIN	1FADP3K25JL227788
Claim reference	CLM-2026-0433

ESTIMATE OF REPAIR COSTS

OPERATION	AMOUNT
Front bumper cover - replace	\$590.00
Nearside headlamp unit - replace	\$880.00
Bonnet - repair and refinish	\$760.00
Radiator grille and mounting - replace	\$410.00
Labour - 14 hours body, 4 hours refinish	\$1,310.00
Parts, paint and sundries subtotal	\$3,950.00
Total estimate	\$3,950.00

This estimate is valid for 30 days. Supplementary work may be identified once panels are removed and must be authorised before it is carried out.