

REPAIRER

Repair facility	Apex Collision Center
Estimate reference	ACC-7781
Estimate date	2026-09-07
Vehicle	2020 Volkswagen Golf TSI (Silver)
VIN	3VW5T7AU4LM049217
Claim reference	CLM-2026-0435

ESTIMATE OF REPAIR COSTS

OPERATION	AMOUNT
Front passenger door skin - replace	\$1,450.00
Front passenger door - refinish	\$780.00
Blend front wing and rear door	\$1,120.00
Door trim, handle and mirror assembly - replace	\$1,390.00
ADAS blind spot sensor - replace and recalibrate	\$1,200.00
Labour - 18 hours	\$1,000.00
Parts, paint and sundries subtotal	\$6,940.00
Total estimate	\$6,940.00

This estimate is valid for 30 days. Supplementary work may be identified once panels are removed and must be authorised before it is carried out.