Incident report IR-2026-031

Filed 12 March 2026 · Field operations

Where	When	Reported by	Technician
Monument Square station, dock 7	12 March 2026, 08:40	A rider, through the app	Jamal Ortiz

What happened

The dock would not release bike 4471. The rider was charged for a ride they could not take. Jamal Ortiz found a worn locking pin. A replacement pin is on order, and dock 7 stays out of service until it is fitted.

Status

Open. A repaired dock goes back into service only after the station manager signs off the repair. The rider's refund follows the refund policy in force on the day of the incident.