
(a) one MZI (dotted: bar)
output power
internal phase θ/π
cross, ideal 50:50
cross, η = 0.45
cross, η = 0.40
(b) mesh: phase errors
infidelity 1 − F
phase error σφ (rad)
N=4: simulated
N=4: 1(N−1)σ²
N=6: simulated
N=6: 1(N−1)σ²
N=8: simulated
N=8: 1(N−1)σ²
(c) mesh: split errors
infidelity 1 − F
coupler error ση
N=4: simulated
N=4: 2(N−1)σ²
N=6: simulated
N=6: 2(N−1)σ²
N=8: simulated
N=8: 2(N−1)σ²