
(a)
wide gap: weak κ_1
narrow gap: strong κ_2
κ_1 κ_2 κ_1 κ_2 κ_1
A B A B A B
one unit cell
(b)
T: weak coupling on both
sides of the centre guide
T
D
D: equal gaps; centre guide detuned by Δ
(c)
arm element = T, D or W,
each with its own random errors
ϕ
50:50
θ
phase
shifter
arm element
arm element
50:50
coupler
coupler