

Automated Warehouse / PLC_1 [CPU 1211C DC/DC/DC] / Program blocks

CTU [FC1]

CTU Properties

General

Name	CTU	Number	1	Type	FC	Language	LAD
Numbering	Automatic						


Information

Title		Author		Comment		Family	
Version	0.1	User-defined ID					


PIC & Plcae Func				
Name	Data type	Default value	Supervision	Comment
Input				
Output				
InOut				
Temp				
Constant				
▼ Return				
CTU	Void			

Network 1


:




Network 2:



Network 3:




Network 4:



Network 5:


```
graph LR; I1_1["%I1.1  
\"Auto\""] --- I0_4["%I0.4  
\"Item Detected\""]; I0_4 --- Q0_4["%Q0.4  
\"Grab\""]; Q0_4 --- I0_3["%I0.3  
\"Moving Z\""]; I0_3 --- I0_2["%I0.2  
\"Moving x\""]; I0_2 --- Q0_3["%Q0.3  
\"Move z\""]; I0_2 --- M0_2["%M0.2  
\"Moving x mem 1\""];
```



Network 6:


```

graph LR
    I1_1["%I1.1  
\"Auto\""] --- Q0_2["%Q0.2  
\"Move X\""]
    Q0_2 --- I0_1["%I0.1  
\"Item at Exit\""]
    I0_1 --- I0_3["%I0.3  
\"Moving Z\""]
    I0_3 --- M0_3["%M0.3  
\"Tag_1\""]
    I0_3 --- Branch
    Branch --- Q0_4["%Q0.4  
\"Grab\""]
    Branch --- Q0_3["%Q0.3  
\"Move z\""]
    Branch --- Q0_2_2["%Q0.2  
\"Move X\""]
  
```



Network 7:

```
graph LR; I11["%I1.1  
\"Auto\""] --- Q04["%Q0.4  
\"Grab\""]; Q04 --- I01["%I0.1  
\"Item at Exit\""]; I01 --- Q00_top["%Q0.0  
\"Entry Conveyor\""]; I01 --- Q00_bot["%Q0.0  
\"Entry Conveyor\""]; Q00_top --- Q01["%Q0.1  
\"Exit Conveyor\""]; Q00_bot --- Q01;
```



Network 8:

