
1-pose reach capture vs frame rate and tremor
never completes
12
10
8
6
4
2
time to calibration done [s]
tremor σ = 0 mm
tremor σ = 5 mm
tremor σ = 10 mm
tremor σ = 20 mm
3
5
8
15
30
60
teleop_frame rate [Hz]