
P2a — lag = kd/kp (what teleop feels)
tracking lag [ms]
bandwidth w_n [rad/s]
zeta=0.7
zeta=0.85
zeta=1.0
zeta=1.3
P2b — ringing
overshoot [%]
bandwidth w_n [rad/s]
P2c — stiction floor
steady-state error [mrad]
bandwidth w_n [rad/s]
P2d — the cost of stiffness
torque RMS on 2 mrad jitter [% of F_lim]
bandwidth w_n [rad/s]