
impedance step (Right Arm 4, +23°)
joint step response [deg]
time [s]
K=20
K=50
K=100
push 1.5 s then release
palm displacement [cm]
time [s]
impedance K=50
compliance (holds)
torque soft wall (30 N drag into torso)
min capsule gap [cm]
time [s]
guard ON
guard OFF