```
/* Skrevet af Nicolai Glud
Init.h */
#include "device.h"

/* Set Control pins of accelerometer ENABLE=1, MODE=1, ST/MODE=LOW */
#define ACCL_SET_CONTROL ((uint8) 0x06)

void init( void );
```