## THE SPAR GROUP LTD



02-Feb-2017

Maruis Stassen Porterville SPAR Voortrekker Street Porterville 6810

Portspa@intekom.co.za 022 931-2150

## An audit has been carried out in the following store:

Porterville SPAR

Store audit date and time:

02-Feb-2017 Date:

The following is a report highlighting very important to critical issues found during the audit for your attention (excluding pictures). Kindly note that a full report inclusive of pictures will follow in due course.

The overall rating achieved in each department audited is recorded in the attached report, if any issues are raised they will be listed below each department heading.

Yours Sincerely,

**Group Property Portfolio Manager** 

22 Chancery Lane, Pinetown 3610 Tel: 031 719 1900 Fax: 031 719 1990 P.O. Box 1589, Pinetown 3600 Website: http://www.spar.co.za

NON-EXECUTIVE DIRECTORS: M.J. Hankinson (Chairman), P.K. Hughes, R.J. Hutchison, M.P. Madi, H.K. Mehta, P. Mnganga, C.F. Wells
EXECUTIVE DIRECTORS: G.O. OComnor (Chief Executive), M.W. Godfrey, W.A. Hook, R. Venter COMPANY SECRETARY: K.J. O'Brien
EXECUTIVE MANAGEMENT COMMITTEE: G.O. O'Comnor (Chief Executive), D.C. Sorrageiro, B. Nosten, W.H. Brown, T.D. Gurrie, M.W. Godfrey, W.A. Hook, C.L. Isaac, K.J. O'Brien (Company Secretary),
R.G. Philipson, M.G. Prentice, M.M. Santana, E.P. Stelma (Dutch), S.A.T.Tabudi, R. Venter, R. de Vos, R.E. Whitmore













## THE SPAR GROUP LTD



Store Name Porterville SPAR Wendy **Auditor Name** Naidu

**Store Address** Voortrekker Street Porterville 6810

> Landlord Kleinvlei Trust

Manager on Duty Kevin Harvey Retailer

**Landlord Contact Details** 0218526815 **Landlord Address Details** 

Maruis Stassen

26 Andries Pretorius | Bellville | 7530 | P O Box 4751

Portspa@intekom.co.za

**Landlord Email Details** trust@maree3.co.za

| Tyger Valley | 7536

Senior ROM Gerald Dube **Senior ROM Contact Details** 0836764770

gerald.dube@spar.co.za

**Audit Date** 02-Feb-2017

**Email Address** 

Very Bad Replacement Programme 1 Rehabilitation Bad 2 Rehabilitation Programme To be monitored for further 3.5 Requires Constant Condition-based Maintenance 4 Maintenance programme Very Good 5 Preventative Maintenanc

ABLUTION / SHOWER ISSUE

Identified Issue 1: Ballasts

Rating 1: Identified Issue 2: Light Fitting

Rating 2:

Comment / Action To Take: Broken | Replace | Repair

There is also a ballast broken in the customer ablution. Additional Comments:

ABLUTION / SHOWER ISSUE

Identified Issue 1: Window Latches

Rating 1:

Comment / Action To Take: Broken | Replace

**Additional Comments:** 

ADMIN AREA ISSUES

**Identified Issue 1:** Fire Equipment

Rating 1:

Comment / Action To Take:

**Additional Comments:** 

Missing | Reinstate | Fire & Safety Hazard | Non-Compliant | Will invalidate insurance cover over the

BAKERY AREA ISSUES Identified Issue 1: Door Frames Rating 1: **Identified Issue 2:** Doors Rating 2: **Identified Issue 3:** Door Locks Rating 3: 1

Identified Issue 4: Door Handles

Rating 4:

Comment / Action To Take: Missing | Reinstate | Damaged | Repair | Was Raised In Previous Audit

Additional Comments:

**BUTCHERY AREA ISSUES** 

Identified Issue 1:DoorsRating 1:1

Identified Issue 2: Door Frames

Rating 2:

Comment / Action To Take: Broken | Damaged | Water logged | Replace

**Additional Comments:** 

BUTCHERY AREA ISSUES

Identified Issue 1: Fat Traps
Rating 1: 1

Comment / Action To Take: Broken | Repair

**Additional Comments:** 

CANTEEN AREA ISSUES

Identified Issue 1: Door Handles

Rating 1:

Identified Issue 2: Door Locks

Rating 2:

Comment / Action To Take: Missing | Replace

**Additional Comments:** 

EXTERIOR ISSUES

Identified Issue 1: Flags / Poles

Rating 1:

Comment / Action To Take: Fading | Replace blanks

**Additional Comments:** 

FRESH PRODUCE PREP AREA ISSUES

Identified Issue 1: Metal Corner Protectors

Rating 1: 1
Identified Issue 2: Walls
Rating 2: 3

Comment / Action To Take: Damaged | Missing | Replace | Suggest Aluminium Treadplate Be Installed

Additional Comments: Suggest aluminium tread platting be installed to prevent further damage to walls.

RECEIVING / STOREROOM

RECEIVING / STOREROOM Overall Rating: 3

RECEIVING / STOREROOM ISSUES

Identified Issue 1: Distribution Board

1

Rating 1:

Identified Issue 2: Labelling
Rating 2: 1

Identified Issue 3: Covers Missing
Rating 3: 1

Comment / Action To Take: To be labelled | Replace | Fire & Safety Hazard | Non-Compliant | Will invalidate insurance cover Additional Comments:

RECEIVING / STOREROOM ISSUES

Identified Issue 1: Fire Equipment

Rating 1: 1

Identified Issue 2: Fire Escape Doors

Rating 2: 1

Comment / Action To Take: Not Serviced | Requires Servicing | Not to be obstructed 24/7/365 | Fire & Safety

Additional Comments:

Identified Issue 1:	Light
Rating 1:	1
Identified Issue 2:	Ballasts
Rating 2:	1
Identified Issue 3:	Lights Covers
Rating 3:	1
Comment / Action To Take:	Broken   Damaged   Fused   Missing   Replace
Additional Comments:	Lighting in very poor condition. The Retailer must attend to items listed. Cable trays damaged to be repaired.