

**MFE SERVICES SDN. BHD.** (952723-P)

No. 2339, Jalan Raja, Mukim Sungai Raya, 84300 Muar, Johor Darul Ta'zim.
Tel : 06-985 6988 / 985 8709 · Fax : 06-985 9806 · Email : mfetsb@gmail.com

Report No.	
Job Ref.	SV-20260906-41
Issued	

FIRE SYSTEM SERVICE REPORT

FIRE FIGHTING & PROTECTION SYSTEM — MAINTENANCE, INSPECTION & TESTING

CLIENT	DEMO-V7-SHARED-EVIDENCE		
SITE / ADDRESS	Primary Service Site		
TELEPHONE / FAX		CONTACT PERSON	
DATE OF SERVICE	2026-09-06	ARRIVAL / DEPARTURE	
SERVICE CALL NO.		CONTRACT NO.	
FREQUENCY		SERVICE STATUS	☒ COMPLETED ☐ TO BE CONTINUED
TEST LEADER	technician-demo	TECHNICIANS	technician-demo

FIRE FIGHTING & PROTECTION SYSTEMS SERVICED

☒ Automatic Sprinkler System	☒ Hose Reel System	☒ Fire Alarm / Detector System	☒ Hydrant System
☒ Portable Fire Extinguisher	☐ Dry / Wet Riser System	☐ CO2 Fire Extinguisher System	☐ Wet Chemical System
☐ FM 200 System	☐ Smoke Ventilation System	☐ Fire Intercom System	☐ Fire Rated Roller Shutter

WE HEREBY CONFIRM THAT THE ATTACHED RECORDS ARE TRUE AND CORRECT AS AT THE TIME OF INSPECTION / TESTING.

SERVICED BY — MFE SERVICES SDN. BHD.	VERIFIED BY — MFE SERVICES SDN. BHD.	CONFIRMED BY — CUSTOMER
technician-demo Team: Signature · Date: 2026-09-06	 Name, Signature & Company Stamp · Date:	 Name, Signature & Company Stamp · Date:

Customer Satisfaction / Comment	☐ Excellent	☐ Satisfactory	☐ Not Satisfactory	Comment:
---------------------------------	------------------------------------	---------------------------------------	---	----------

NOTE :-

1. All fire systems listed above were tested and inspected on the date of service. Detailed results are recorded on the following pages.
2. Should any abnormal condition occur which might cause further damage to the customer's systems or threaten human safety or the environment, the customer agrees to call MFE immediately for necessary action.
3. Rectification works, parts replacement, piping and wiring works found necessary during this service are quoted and charged separately.
4. MFE is not responsible for any area, room or device that was not made accessible for inspection or testing on the date of service.

S	SUMMARY OF TESTING One line per system inspected. The condition is the overall result of that system; details are on the page shown.	DATE OF SERVICE 2026-09-06

NO.	SYSTEM / TEST DESCRIPTION	LOCATION / UNIT	PAGE	FREQUENCY	CONDITION	MAIN FINDING
1	AUTOMATIC SPRINKLER SYSTEM		3		FAILED	Pump House — Stand-By Pump Water, Oil, Fuel, Belt and etc: NOT GOOD — 2 (+3 more)
2	HOSE REEL SYSTEM		6		FAILED	Pump House — Stand-by Pump Cut In: NOT GOOD — 31 (+1 more)
3	FIRE ALARM / DETECTOR SYSTEM		8		FAILED	Main Function Key — Main Alarm Reset: NOT GOOD — 2 (+1 more)
4	HYDRANT SYSTEM		10		FAILED	Hydrant Set — No. 1 (1) — Diffuser Nozzle: NOT GOOD — 1 (+2 more)
5	PORTABLE FIRE EXTINGUISHER		11		GOOD CONDITIONS	—

CONDITION INDICATOR

GOOD CONDITIONS	All items in good working condition; system ready for use.
REFER DETAIL PAGE	Defect found and rectified / minor defect; system usable during a fire emergency. See detail page.
FAILED	Defect found that affects the system. Rectification required; see detail page.

RESULT SYMBOLS (DETAIL PAGES)

✓ GOOD	In good working condition / Baik
✗ NOT GOOD	In poor working condition / Tidak Memuaskan
○ COMPLETE REPAIR	Defect rectified on site / Siap Baik Pulih
– N/A	No need checking / Tidak Berkaitan

ADVICE TO CUSTOMER :-

1. Replace fire alarm panel and pump starter batteries every 2 years or when capacity test fails, using the same ampere-hour rating.

2. Do not block fire protection equipment, alarm devices, exit doors, fire lift lobbies, staircases or escape routes. Do not padlock exit doors.

3. Emergency lights and KELUAR signs must be kept in working condition.

4. Do not use fire system water (hose reel, hydrant, riser, fire tank) except for fire fighting.
5. Do not isolate or switch off any fire alarm panel, pump set or suppression panel without informing MFE.

6. After any renovation shut-down, ensure all control valves are returned to the OPEN position.

7. Refill or replace any portable fire extinguisher immediately after use.

8. Contact MFE at 06-985 6988 for any complaint about this service.

1	AUTOMATIC SPRINKLER SYSTEM	SYSTEM CONDITION FAILED
---	----------------------------	-----------------------------------

• Do not close any main control valve. Valves are secured with MFE safety seals.

WATER TANK

NO	INSPECTION & TEST	RESULT
1	S.A.J Main Water Supply	✓ GOOD
2	Water Level	✓ GOOD
3	Automatic Refilling Facilities	✓ GOOD
4	Drain Valve In Close Position And All Stop Valve In Open Position	✓ GOOD

PUMP HOUSE CHECKS

NO	INSPECTION & TEST	RESULT	REMARKS
1	Keep Clean In Pump House	✓ GOOD	
2	Manual Start Jockey Pump, Duty Pump & Stand-by Pump	- N/A	1
3	Stand-By Pump Water, Oil, Fuel, Belt and etc	✗ NOT GOOD	2
4	Correct Operation Of Battery Charging Alternator	- N/A	
5	Battery In Good Serviceable	- N/A	
6	Pump Run / Phase Failure Alarm Signal To Main Alarm Panel	- N/A	
7	Jockey Duty And Stand-By Pump In Auto Start Position	- N/A	
8	Test Valve In Close Position And All Gate Valve In Open Position	- N/A	

PUMP PRESSURE MEASUREMENTS

NO	INSPECTION & TEST	REQ / UNIT	READING	RESULT	REMARKS
1	Jockey Correct Cut In / Cut Out	PSI	Cut In 1 / Cut Out 1	○ COMPLETE REPAIR	1
2	Correct Duty Pump Cut In	PSI	1	○ COMPLETE REPAIR	1
3	Correct Stand-By Pump Cut In	PSI	2	✗ NOT GOOD	asd

MAIN ALARM VALVE CHECKS

NO	INSPECTION & TEST	RESULT
1	Breaching Inlet In Good Serviceable	- N/A
2	Alarm Gong In Function	- N/A
3	Flow Meter Valve In Close Position And All Valve In Open Position	- N/A

AUTOMATIC SPRINKLER SYSTEM (continued)

FAILED

TEST RUN FIRE PUMP 30 MINUTES


NO	INSPECTION & TEST	REQ / UNIT	READING	RESULT
1	Water Supply Gauge At	PSI	3	- N/A
2	Installation Gauge At	PSI	4	- N/A

DESCRIPTION	REQ / UNIT	JOCKEY PUMP	DUTY PUMP	STANDBY PUMP
Test Run Fire Pump 30 Minutes		- N/A	- N/A	- N/A


1. Pump House — Stand-By Pump Water, Oil, Fuel, Belt and etc: NOT GOOD — 2
2. Pump House — Jockey Correct Cut In / Cut Out: COMPLETE REPAIR — 1
3. Pump House — Correct Duty Pump Cut In: COMPLETE REPAIR — 1
4. Pump House — Correct Stand-By Pump Cut In: NOT GOOD — asd

55

1. Pump House - Stand-by Pump Water, Oil, Fuel, Belt and Other Service Items



2. Pump House - Duty Pump Cut In



3. Pump House - Jockey Pump

1	AUTOMATIC SPRINKLER SYSTEM (continued)	SYSTEM CONDITION FAILED
---	--	-----------------------------------



4. Pump House - Stand-by Pump Cut In

INSPECTION DATE	2026-09-06	INSPECTED BY	technician-demo	
INITIAL				

2	HOSE REEL SYSTEM	SYSTEM CONDITION FAILED
---	------------------	-----------------------------------

WATER TANK

NO	INSPECTION & TEST	RESULT	REMARKS
1	S.A.J Main Water Supply	✓ GOOD	
2	Water Level	✓ GOOD	
3	Automatic Refilling Facilities	○ COMPLETE REPAIR	123
4	Drain Valve In Close Position And All Stop Valve In Open Position	- N/A	

PUMP HOUSE CHECKS

NO	INSPECTION & TEST	RESULT
1	Keep Clean In Pump House	✓ GOOD
2	Stand-By Pump Oil, Fuel and Other Service Items	✓ GOOD
3	Battery Charger Power Failure Alarm	✓ GOOD
4	Battery In Good Serviceable / Function	✓ GOOD
5	Pump Run / Failure Alarm To Fire Alarm Panel	✓ GOOD
6	Jockey And Stand-By Pump In Auto Start Position	✓ GOOD
7	Test Valve In Close Position And All Gate Valve In Open Position	✓ GOOD

PUMP PRESSURE MEASUREMENTS

NO	INSPECTION & TEST	REQ / UNIT	READING	RESULT	REMARKS
1	Jockey Pump	PSI	Cut In 1 / Cut Out 1	✓ GOOD	
2	Stand-by Pump Cut In	PSI	-1	✗ NOT GOOD	31

TEST RUN FIRE PUMP 30 MINUTES

DESCRIPTION	REQ / UNIT	DUTY PUMP	STANDBY PUMP
Test Run Fire Pump 30 Minutes		✓ GOOD	✓ GOOD

DRUM TYPE

NO	INSPECTION & TEST	REQ / UNIT	READING	RESULT
1	Drum Type		Swing	

2	HOSE REEL SYSTEM (continued)	SYSTEM CONDITION FAILED
---	------------------------------	-----------------------------------

HOSE REEL LOCATION ROWS

NO.	LOCATION	DRUM	HOSE	NOZZLE	VALVE	NOZZLE BOX	REMARKS
1	1	✓ GOOD	✓ GOOD	✓ GOOD	✓ GOOD	✓ GOOD	

REMARK :
1. Water Tank — Automatic Refilling Facilities: COMPLETE REPAIR — 123
2. Pump House — Stand-by Pump Cut In: NOT GOOD — 31

COMMENTS

1

PHOTO EVIDENCE

	
1. Water Tank - Automatic Refilling Facilities	2. Pump House - Stand-by Pump Cut In

INSPECTION DATE	2026-09-06	INSPECTED BY	technician-demo	
INITIAL				

3	FIRE ALARM / DETECTOR SYSTEM	SYSTEM CONDITION FAILED
---	------------------------------	-----------------------------------

- Do not isolate any switch at the control panel without permission.
- Do not replace batteries with a lower ampere-hour rating than the original.

CONTROL PANEL LOCATION

NO	INSPECTION & TEST	REQ / UNIT	READING	RESULT
1	Control Panel Location		1	

ZONE AND DEVICE ROWS

NO.	ALARM ZONE	LOCATION	MANUAL CALL POINT			FLOW SWITCH			HEAT DETECTOR			SMOKE DETECTOR			REMARKS
			N	T	I	N	T	I	N	T	I	N	T	I	
1	1	1	✓			✓			✓			✓			

CHARGER & BATTERIES

NO	INSPECTION & TEST	RESULT	REMARKS
1	Main Supply	✓ GOOD	
2	Battery	- N/A	
3	Charger	○ COMPLETE REPAIR	3

MAIN FUNCTION KEY

NO	INSPECTION & TEST	RESULT	REMARKS
1	Main Alarm Reset	✗ NOT GOOD	2
2	Lamp Test	✓ GOOD	
3	Evacuate	✓ GOOD	
4	A/C Supply	✓ GOOD	
5	D/C Supply	✓ GOOD	
6	SPKA System	✓ GOOD	
7	Alarm Lift Trip	✓ GOOD	
8	Signal Gas Discharge	✓ GOOD	



ALARM DEVICES

3	FIRE ALARM / DETECTOR SYSTEM (continued)	SYSTEM CONDITION FAILED
---	--	----------------------------

NO.	LOCATION	ALARM BELL	MANUAL CALL POINT	REMARKS
123	23	✓ GOOD	✓ GOOD	123

REMARK : 1. Charger & Batteries — Charger: COMPLETE REPAIR — 3 2. Main Function Key — Main Alarm Reset: NOT GOOD — 2
--

COMMENTS 132

PHOTO EVIDENCE	
	
1. Charger & Batteries - Charger	2. Main Function Key - Main Alarm Reset

INSPECTION DATE	2026-09-06	INSPECTED BY	technician-demo	
INITIAL				

4	HYDRANT SYSTEM	SYSTEM CONDITION FAILED
---	----------------	-----------------------------------

HYDRANT TYPE

NO	INSPECTION & TEST	REQ / UNIT	READING	RESULT
1	Hydrant Type		Meter	

HYDRANT LOCATION ROWS


NO.	LOCATION	CANVAS HOSE 1	CANVAS HOSE 2	DIFFUSER NOZZLE	LANDING VALVE	LANDING VALVE HANDLE	HOSE CABINET	KEY LOCK	REMARKS
1	1	✓ GOOD	✓ GOOD	✗ NOT GOOD 1	○ COMPLETE REPAIR 23	○ COMPLETE REPAIR 123	✓ GOOD	✓ GOOD	1

REMARK : 1. Hydrant Set — No. 1 (1) — Diffuser Nozzle: NOT GOOD — 1 2. Hydrant Set — No. 1 (1) — Landing Valve: COMPLETE REPAIR — 23 3. Hydrant Set — No. 1 (1) — Landing Valve Handle: COMPLETE REPAIR — 123	PARTS / RECTIFICATION REQUIRED : 1. DIFFUSER NOZZLE X 1
---	---

COMMENTS

1

PHOTO EVIDENCE

		
1. Hydrant Set - Diffuser Nozzle	2. Hydrant Set - Landing Valve	3. Hydrant Set - Landing Valve Handle

INSPECTION DATE	2026-09-06	INSPECTED BY	technician-demo	
INITIAL				

5	PORTABLE FIRE EXTINGUISHER	SYSTEM CONDITION GOOD CONDITIONS
---	----------------------------	-------------------------------------

PORTABLE FIRE EXTINGUISHER QUANTITIES

TYPE	QUANTITY
Total Fire Extinguisher	1
9KG Dry Powder Fire Extinguisher	1
2KG CO2 Portable Fire Extinguisher	0
Others	1

REMARK : No defects found.

COMMENTS

2

INSPECTION DATE	2026-09-06	INSPECTED BY	technician-demo	
INITIAL				

— END OF REPORT —