
#### JKW boards – Confusion avoidance chart ©


LEDv1.1 / Motor v1.1 / preSalsa / Salsa / Salsa II / Queso DIP


Function  X = possible - = not possible * = 'Or' E.g. Motor OR Mosfet / Optional	Motor v1.1	LEDv1.1	PreSalsa	Salsa	Salsa II	Queso
Screw terminals that connects an external power supply to CHIP CHR-IN	Х	Х	Х	Х	Х	Х
Controller connected via I2C	-	Х	Х	Х	Х	-
Pins for driving ws2812 LEDs	-	Х	Х	Х	Х	-
Pins for analog reading	-	Х	Х	Х	Х	-
"Real-time" GPIOs	-	Х	Х	Х	Х	-
Mosfets to dim a lot of LEDs	-	4	4*	4*	4*/2X	-
Motor driver Channels	2	-	2*	2*	2*/1X	-
Input for "High voltage" (~7V for the Motor)	Х	-	-	-	X	-
Internal connection to CHIP power button pin, e.g. to start the CHIP from power off, or to shut the CHIP down	-	-	-	Х	Х	÷
"Seamless power" (run on CHIP battery, with CHIP powered down)	-	-	-	-	Х	-
Option for onboard power supply (DC in 7-28V)	-	-	-	-	х	Х
CHIP pins used by board (besides I2C bus which is not exclusively used)	*4	*1	*5	*6	*6	-
On board Ws2812 LED option	-	-	-	*	*	-
On board general purpose button (e.g. shutdown for CHIP?)	-	-	-	-	*	-
On board general purpose LED	-	-	Х	*	*	-
4x USB Hub	-	-	-	-	-	Х


preSalsa, Salsa and Salsa II can all be assembled as Dual-channel (4 outputs) Motor driver OR 4-channel Mosfet - PWM Driver (Salsa II can be configured as 1 channel motor AND 2 channel Mosfet - PWM)











Salsa II DIP


ORDERED 2016/03/03

Configuration PWM dimmer Configuration Motor driver

## Queso DIP v4.3

Photos

ORDERED 2016/03/01 EXPECTED 2<sup>nd</sup> Week of April




**Test-board-photos** 






PinOut



# ORDERED 2016/03/16 NOT YET RECEIVED



### ONION DIP v1.0

**Battery pins** 

PINOUT1/2

Screw terminal for power in

# ORDERED 2016/03/16 NOT YET RECEIVED

Standard USB-UART Connector

Stand-alone tinker area for DIL ICs with power rails left & right

Optional: DC-DC regulator to power the CHIP from 7-28V DC, covering tinker area

Optional: Relay to switch e.g. 110/230V AC Power lines @ 10A

Screw terminal for Relay contacts: N\_close, In, N\_open Optional: MOSFET on P0 (active high) to drive the relay

3x LED, P0 &P3 active low,
On Relay closed


GPIO PO-P5, each pin twice

2x SPI-2


2x I2C-2

# ORDERED 2016/03/16 NOT YET RECEIVED


**GND** Rails highlighted



5V Rails highlighted



CHIP 3.3V Rails




# Old boards


The following pages show old boards, which are not longer produced:


- LED DIP v1.1
- preSalsa DIP
- Salsa I
- Motor Dip v1.1

## LED DIP v1.1

Photo











### LED DIP v1.1


**PinOut** 







# preSalsa DIP

Motor Version ->



LED Driver / Mosfet Version






## preSalsa DIP

PinOut

Atmega pin	DIP pin	Arduino Pin	Digital IN/OUT	Analog IN	PWM out	WS2812 support	C.H.I.P. connection
PD7	P12	7	×	1	1	×	ı
PB0	P11	∞	×	ı	ı	×	ı
PC3	P10	17	×	×	•	ı	ı
PD3	6d	3	×	ı	×	×	ı
PC2	P8	16	×	×	ı	ı	ı
PB3	Р7	11	×	1	×	×	ı
PD2	9d	2	×	•	•	×	ı
	P5	1	ı	,	1	ı	×
PC1	P4	15	×	×	•	•	ı
PD5	P3	2	$\underset{*}{\times}$	,	×	*	ı
PD6	P2	9	$\underset{*}{\times}$	•	×	*	ı
PB1	P1	6	$\underset{*}{\times}$		×	*	ı
PB2	PO	10	* × *	•	×	*	ı




## PreSalsa

### **Jumper Config**

diffper coring					
SJ	Function	C 1 1			
1	<ul><li>Vin to Charge in</li><li>If your input voltage is 5V close this jumper. Your Vin will charge your Battery</li></ul>	SJ1			
2	<ul> <li>Vout to Vcc</li> <li>If your Vin is not 5V close it, to get CHIPs 5V on the output</li> <li>If your Vin is 5V and you close SJ5, close this one to power the DIP from the VIN, in this case you must leave SJ3 and SJ4 open!</li> </ul>				
3	<ul> <li>CHIP 5V to Vcc (bot)</li> <li>If you won't power the DIP via VIN, close this jumper to supply 5V power via the CHIP</li> <li>If you've destroyed your CHIP onboard 5V, close it to supply power to the USB ©</li> </ul>		S		
4	<ul> <li>CHIP 3.3V to Vcc (bot)</li> <li>If you want to work the DIP on the (limited) 3.3V of the CHIP</li> </ul>				
5	Vin to Vout  • To forward your input to the output				
Combine: SJ1 + SJ5 + SJ2 if your Vin is 5V SJ2 + SJ3 if you only draw a few mA to use the CHIPs 5V					

**Never combine:** SJ3 and SJ4 or SJ4 + SJ2 + SJ5 and supply power via Vin/Vout or SJ3 + SJ2 + SJ5 and supply power via Vin/Vout or SJ1 if your Vin is NOT ~5V or SJ2 + SJ5 if your **Vin > 5V** 




Salsa DIP

WAITING ON CHINA POST ORDERED 2016/02/10

Configuration PWM dimmer Configuration Motor driver


Atmega pin	DIP pin	Arduino Pin	Digital IN/OUT	Analog IN	PWM out	WS2812 support	C.H.I.P. pin	Motor Pins
PCO	P16	14	×	ı	ı	1	1	
PD4	P15	4	×	1	,	ı	ı	•
PB5	P14	13	×	í	ı	í	ſ	Ы
PB4	P13	12	×	ı	1	ı	ı	DR
PD7	P12	7	×	í	ı	×	í	
PB0	P11	∞	×	ı	ı	×	ı	
PC3	P10	17	×	×	ı	ı	1	
PD3	P9	33	×	,	×	×	ı	ER
PC2	84 84	16	×	×	ı	ı	1	
PB3	Р7	11	×	ī	×	×	ī	
PD2	9e	2	×	ı	ı	×	ı	•
	P5		1	ı	ı	'	×	•
PC1	P4	15	×	×	ı	ı	ı	•
PD5	Ь3	2	× *	ı	×	*	ı	×
PD6	P2	9	× *	1	×	*	ı	
PB1 P	P1	6	× *	,	×	*	,	1
PB2	P0	10	× *	1	×	*	1	딥



## Motor DIP v1.1

Photos






### Motor DIP v1.1

Pin Out


#	Function
Vin	Logic voltage, 5V
Р0	Channel 1 direction
P1	Channel <b>1 enable</b>
P2	Channel 3 direction
Р3	Channel <b>3 enable</b>
GND	Ground for logic voltage
VHin	"High" voltage for Motor (5-36 Volt), can be connected to Vin
P4	Channel 1 output
P5	Channel <b>2 output</b> (inverse of channel 1)
P6	Channel 3 output
P7	Channel <b>4 output</b> (inverse of channel 3)
GND	Ground for "high" voltage



### Motor DIP v1.1

**Jumper Config** 

SJ	Function
1-4	<ul> <li>Use CHIP GPIO as input</li> <li>Close them, if you use the CHIP GPIO to generate the control signals.</li> <li>Leave them open if you want to use the screw header</li> </ul>
5	<ul> <li>Vin to Charge in</li> <li>Close it if you Vin is 5V from a power supply or external battery to power this CHIP over this pin as well</li> <li>Leave it open, if you feed the CHIP 5V to the Vin</li> </ul>



# More photos



